

# DILL TPMS APPLICATIONS CHART ©

(Row Color designates the required replacement parts kit for the OE sensor.)

Make	Model	Model Year Range	OE Torque In-Lbs	Dill Replacement Sensor	Dill OEM Sensor	Dill Kit	Valve Stem Replacement	Simplified Relearn
Acura	CSX	08-11	35	7002 or 7002A	1212	2045K	NO	OBDII required
Acura	ILX	13-15	71	7002 or 7002A	5513	7000K	VS70	OBDII required
Acura	ILX	16-18	71		5514	7000K	VS70	Auto-relearn
Acura	ILX	19	---		NEW	VS20	VS20	Auto-relearn
Acura	MDX	04-06	40	7002A	1057	2000K	1096	Auto-relearn
Acura	MDX	07-13	35	7002A	1209	1100K	NO	Auto-relearn
Acura	MDX	14-15	71		5512	7000K	VS70	Auto-relearn
Acura	MDX	16-19	71		5514	7000K	VS70	Auto-relearn
Acura	NSX	16-19	71		3751	7000K	VS70	Dealer OBD only
Acura	RDX	07-12	35	7002A	1209	1100K	NO	Auto-relearn
Acura	RDX	13-15	71		5512	7000K	VS70	Auto-relearn
Acura	RDX	16-18	71		5514	7000K	VS70	Auto-relearn
Acura	RDX	19	71		3751	7000K	VS70	Auto-relearn
Acura	RL	05-08	40	7002A	1057	2000K	1096	Auto-relearn
Acura	RL	09-12	40	7002A	1057	2045K or 2000K	None or 1096	Auto-relearn
Acura	RLX	14-15	35	7002A	1214	2045K	NO	Auto-relearn
Acura	RLX	16-19	71		5512	7000K	VS70	Auto-relearn
Acura	TL	06-08	40	7002A	1057	2000K	1096	Auto-relearn
Acura	TL	09-14	35	7002A	1214	2045K	NO	Auto-relearn
Acura	TLX	15-17	71		5514	7000K	VS70	Auto-relearn
Acura	TLX	18-19	71		3751	7000K	VS70	Auto-relearn
Acura	TSX	07-14	35	7002A	1209	1100K	NO	Auto-relearn
Acura	ZDX	10-13	35	7002A	1214	2045K	NO	Auto-relearn
Alfa Romeo	4C	15-18	71	5001	9214	1100K	VS40	Auto-relearn
Alfa Romeo	8C Competizione	09-10	35		9001	1090K	1092 or 1094	
Alfa Romeo	Giulia	17-19	71	5001	2495	7000K	VS70	Auto-relearn
Alfa Romeo	Stelvio	18	71	5001	2495	7000K	VS70	Auto-relearn
Audi	Allroad	02-05	35		9004	1090K	1092 or 1099L	No tools needed
Audi	A3	08-11	71	7003 or 7003A*	1053	1030K	NO	Trigger required'
Audi	A4	05-08	35		9011	1090K	1092	No tools needed
Audi	A4 cabrio	09	35		9011	1090K	1092	No tools needed
Audi	A4 4-door	09	71	7003 or 7003A*	1053	1030K	NO	Trigger required'
Audi	A5	08-09	71	7003 or 7003A*	1053	1030K	NO	Trigger required'
Audi	A6	05-08	35		9011	1090K	1092	No tools needed
Audi	A8	02-03	35		9004	1090K	1092	No tools needed
Audi	A8	04-09	35		9001	1090K	1092	No tools needed
Audi	Q5	09	71	7003 or 7003A*	1053	1030K	NO	Trigger required'
Audi	Q7	07-09	35		9011	1090K	1092	No tools needed
Audi	R8	08-09	35		9011	1090K	1092	No tools needed
Audi	R8	10-18	40		9011	1096	1096	No tools needed
Audi	RS3	17-18	40	5001	9018	1096	1096	No tools needed
Audi	RS4	07-08	35		9011	1090K	1092	No tools needed
Audi	RS5	18	40	5001	9018	1096	1096	No tools needed
Audi	RS6	03	35		9004	1090K	1092	No tools needed
Audi	RS7	14-18	40		9011	1096	1096	No tools needed
Audi	S4	05-09	35		9011	1090K	1092	No tools needed
Audi	S5	08-09	71	7003 or 7003A*	1053	1030K	NO	Trigger required'
Audi	S6	07-09	35		9011	1090K	1092	No tools needed
Audi	S8	02-03	35		9004	1090K	1092	No tools needed
Audi	S8	07-09	35		9001	1090K	1092	No tools needed
Audi	S8	16-18	40		9011	1096	1096	No tools needed
Audi	SQ5	14-16	40		9011	1096	1096	No tools needed
Audi	TT	08-10	71	7003 or 7003A*	1053	1030K	NO	Trigger required'
Audi	TT RS	18	40	5001	9018	1096	1096	No tools needed
*	Note: 7003A must be scanned while pressurized before the vehicle is driven.							
Bentley	Arnage	02-03	35		9001	1090K	1092-1095	
Bentley	Arnage	04-09	35		9011	1090K	1092-1095	
Bentley	Azure	07-10	35		9011	1090K	1092-1095	
Bentley	Bentayga	17-19	40	5001	9018	1096	1096	
Bentley	Brooklands Coupe	08-09	35		9011	1090K	1092-1095	
Bentley	Continental GT	04-05	35		9001	1090K	1092-1095	
Bentley	Continental GT (Post May 2005)	05-10	35		9011	1090K	1092-1095	
Bentley	Continental GT	11-18	40		9011	1096	1096	
Bentley	Flying Spur	06-10	35		9011	1090K	1092-1095	
Bentley	Flying Spur	11-18	40		9011	1096	1096	
Bentley	Mulsanne	11-17	40		9011	1096	1096	
BMW	1 Series	08-11	35		1027	1090K	1092-1095	No tools needed
BMW	1 Series (Post Sept. 2010)	11-13	40	5001	9012	1096	1096	No tools needed

Verify Model Year by checking the 10th digit in the VIN: 8 = 2008MY, 9 = 2009MY, A = 2010MY, B = 2011MY, etc.  
 Visit [dillvalves.com](http://dillvalves.com) for vehicle look-ups containing parts, pictures, relearns and training videos  
 Need Additional Help? Call 800-815-3455, option 3 for technical support

# DILL TPMS APPLICATIONS CHART ©

(Row Color designates the required replacement parts kit for the OE sensor.)

Make	Model	Model Year Range	OE Torque In-Lbs	Dill Replacement Sensor	Dill OEM Sensor	Dill Kit	Valve Stem Replacement	Simplified Relearn
BMW	2 Series	14	40	5001	9017	1096	1096	No tools needed
BMW	2 Series (Post March 2014)	14-19	71	5001	5256	7020K	VS70	No tools needed
BMW	3 Series	02-06	35		9002	1090K	1092-1095	No tools needed
BMW	3 Series	07-09	35		1027	1090K	1091-1095**	No tools needed
BMW	3 Series	10-11	40	5001	9012	1096	1096	No tools needed
BMW	3 Series 2dr. and Wagon	12-13	40	5001	9012	1096	1096	No tools needed
BMW	3 Series 4dr. Sedan	12-14	40	5001	9017	1096	1096	No tools needed
BMW	3 Series (Post March 2014)	14-18	71	5001	5256	7020K	VS70	No tools needed
BMW	3 Series Gran Turismo	19	71	5001	5256	7020K	VS70	No tools needed
BMW	3 Series wagon	19	71	5001	5256	7020K	VS70	No tools needed
BMW	4 Series	14	40	5001	9017	1096	1096	No tools needed
BMW	4 Series (Post March 2014)	14-19	71	5001	5256	7020K	VS70	No tools needed
BMW	M4 GTS	15-17	40	5001	9017	1096	1096	No tools needed
BMW	5 Series	06-11	35		1027	1090K	1091-1095	No tools needed
BMW	5 Series (Post Sept. 2010)	11-14	40	5001	9012	1096	1096	No tools needed
BMW	5 Series	15-16	40	5001	9017	1096	1096	No tools needed
BMW	5 Series Gran Turismo	17	40	5001	9017	1096	1096	No tools needed
BMW	5 Series	17-19	71	5001	9077	1100K	VS40	No tools needed
BMW	6 Series	06-10	35		1027	1090K	1091-1095	No tools needed
BMW	6 Series	12-14	40	5001	9012	1096	1096	No tools needed
BMW	6 Series (non-G.T.)	15-19	40	5001	9017	1096	1096	No tools needed
BMW	6 Series Gran Turismo	18-19	71	5001	9077	1100K	VS40	No tools needed
BMW	7 Series	02-05	35		9002	1090K	1092-1095	No tools needed
BMW	7 Series	06-11	35		1027	1090K	1091-1095	No tools needed
BMW	7 Series (Post Sept. 2010)	11-14	40	5001	9012	1096	1096	No tools needed
BMW	7 Series	15	40	5001	9017	1096	1096	No tools needed
BMW	7 Series	16-19	71	5001	9077	1100K	VS40	No tools needed
BMW	i3	14-18	71	5001	5256	7020K	VS70	No tools needed
BMW	i8	14-19	71	5001	5256	7020K	VS70	No tools needed
BMW	X1	13-14	40	5001	9012	1096	1096	No tools needed
BMW	X1	15	40	5001	9017	1096	1096	No tools needed
BMW	X1	16-18	71	5001	5256	7020K	VS70	No tools needed
BMW	X2	18	71	5001	5256	7020K	VS70	No tools needed
BMW	X3	06-10	35		1027	1090K	1091-1095	No tools needed
BMW	X3	11-14	40	5001	9012	1096	1096	No tools needed
BMW	X3	15-17	40	5001	9017	1096	1096	No tools needed
BMW	X3	18-19	71	5001	9077	1100K	VS40	No tools needed
BMW	X4	15-18	40	5001	9017	1096	1096	No tools needed
BMW	X4	19	71	5001	9077	1100K	VS40	No tools needed
BMW	X5	07-11	35		1027	1090K	1092-1095	No tools needed
BMW	X5 (Post Oct. 2010)	11-13	40	5001	9012	1096	1096	No tools needed
BMW	X5	14-18	71	5001	5256	7020K	VS70	No tools needed
BMW	X5	19	71	5001	9077	1100K	VS40	No tools needed
BMW	X6	08-11	35		1027	1090K	1092-1095	No tools needed
BMW	X6 (Post Oct. 2010)	11-14	40	5001	9012	1096	1096	No tools needed
BMW	X6	15-19	71	5001	5256	7020K	VS70	No tools needed
BMW	Z Series	07-11	35		1027	1090K	1091-1095	No tools needed
BMW	Z Series (Post Sept. 2010)	11-14	40	5001	9012	1096	1096	No tools needed
BMW	Z4	15-16	40	5001	9017	1096	1096	No tools needed

\*\* Note: 1099 and 1099L are valve options on some special wheel packages.

Buick	Allure	07-08	71	7001HP	7001HP	1050K	NO	Trigger required
Buick	Allure	09	---	7001HP-R	9153	VS950	VS950	Trigger required
Buick	Cascade	16-19	---	7001HP-R	9153	VS950	VS950	Trigger required
Buick	Enclave	08	71	7001HP	7001HP	1050K	NO	Trigger required
Buick	Enclave	09-14	---	7001HP-R	9153	VS950	VS950	Trigger required
Buick	Enclave	15-17	---	7001HP-R	9153	VS20	VS20	Trigger required
Buick	Enclave	18-19	---	5001	6561	VS20	VS20	Trigger required
Buick	Encore	13-15	---	7001HP-R	9153	VS950	VS950	Trigger required
Buick	Encore	16-19	---	7001HP-R	9153	VS20	VS20	Trigger required
Buick	Envision	16-18	---	7001HP-R	9153	VS20	VS20	Trigger required
Buick	Envision	19	---		6164	VS20	VS20	Trigger required
Buick	LaCrosse	07-08	71	7001HP	7001HP	1050K	NO	Trigger required
Buick	LaCrosse	08-15	---	7001HP-R	9153	VS950	VS950	Trigger required
Buick	LaCrosse	16	---	7001HP-R	9153	VS20	VS20	Trigger required
Buick	LaCrosse	17-19	---	5001	9773	VS20	VS20	Trigger required
Buick	Lesabre	07	---	7001HP-R	9153	VS950	VS950	Trigger required
Buick	Lucerne	07-11	---	7001HP-R	9153	VS950	VS950	Trigger required
Buick	Rainier	06-07	62	7001HP	9116	1070K	NO	Trigger required
Buick	Regal	11-16	---	7001HP-R	9153	VS950	VS950	Trigger required

Verify Model Year by checking the 10th digit in the VIN: 8 = 2008MY, 9 = 2009MY, A = 2010MY, B = 2011MY, etc.

Visit [dillvalves.com](http://dillvalves.com) for vehicle look-ups containing parts, pictures, relearns and training videos

Need Additional Help? Call 800-815-3455, option 3 for technical support

**DILL TPMS APPLICATIONS CHART ©**

(Row Color designates the required replacement parts kit for the OE sensor.)

Make	Model	Model Year Range	OE Torque In-Lbs	Dill Replacement Sensor	Dill OEM Sensor	Dill Kit	Valve Stem Replacement	Simplified Relearn
Buick	Regal	17	---	7001HP-R	9153	VS20	VS20	Trigger required
Buick	Regal and TourX	18-19	---	5001	9773	VS20	VS20	Trigger required
Buick	Verano	12-15	---	7001HP-R	9153	VS950	VS950	Trigger required
Buick	Verano	16-17	---	7001HP-R	9153	VS20	VS20	Trigger required
Cadillac	ATS	13	---	7001HP-R	7001HP-R	VS90	VS90	Trigger required
Cadillac	ATS	14-15	---	7001HP-R	9153	VS950	VS950	Trigger required
Cadillac	ATS (snap-in)	16-19	---	7001HP-R	9153	VS20	VS20	Trigger required
Cadillac	ATS Performance	13	62-71	7001HP	7001HP	7020K	VS70	Trigger required
Cadillac	ATS Performance	14-15	62	7001HP	9158	1070K	NO	Trigger required
Cadillac	ATS Performance	16-19	71	7001HP	NEW	2030K	VS40	Trigger required
Cadillac	ATS-V	16-19	71	7001HP	NEW	2030K	VS40	Trigger required
Cadillac	CT6	16-18	---	5001	9773	VS20	VS20	Trigger required
Cadillac	CTS	04-07	62	7001HP	9116	1070K	NO	Trigger required
Cadillac	CTS	08-15	---	7001HP-R	9153	VS950	VS950	Trigger required
Cadillac	CTS	16-19	---	7001HP-R	9153	VS20	VS20	Trigger required
Cadillac	CTS Vsport	14-15	62	7001HP	9158	1070K	NO	Trigger required
Cadillac	CTS Vsport	16-19	71	7001HP	NEW	2030K	VS40	Trigger required
Cadillac	CTS-V	09-15	62	7001HP	9158	1070K	NO	Trigger required
Cadillac	CTS-V	16-19	71	7001HP	NEW	2030K	VS40	Trigger required
Cadillac	Deville	01-05	62	---	9117	1080K	NO	Trigger required
Cadillac	DTS	06	62	7001HP	9158	1070K	NO	Trigger required
Cadillac	DTS	07-11	---	7001HP-R	9153	VS950	VS950	Trigger required
Cadillac	ELR	14	---	7001HP-R	9153	VS950	VS950	Trigger required
Cadillac	ELR	16	---	7001HP-R	9153	VS20	VS20	Trigger required
Cadillac	Escalade	04	62	---	9115	1070K	NO	Trigger required
Cadillac	Escalade	05-06	62	7003 or 7003A	9107	1070K	NO	Trigger required
Cadillac	Escalade	07	62	7001HP	7001HP	2020K	NO	Trigger required
Cadillac	Escalade	07	62	7001HP	9158	1070K	NO	Trigger required
Cadillac	Escalade	07-16	---	7001HP-R	9153	VS950	VS950	Trigger required
Cadillac	Escalade	17	---	7001HP-R	9153	VS20	VS20	Trigger required
Cadillac	Escalade	18-19	---	---	6164	VS20	VS20	Trigger required
Cadillac	Seville	01-04	62	---	9117	1080K	NO	Trigger required
Cadillac	SRX	04-06	62	7001HP	9116	1070K	NO	Trigger required
Cadillac	SRX	07-16	---	7001HP-R	9153	VS950	VS950	Trigger required
Cadillac	STS	05-08	62	7001HP	9076	1070K	NO	Trigger required
Cadillac	STS	09-11	---	7001HP-R	9153	VS950	VS950	Trigger required
Cadillac	STS-V	09	62	7001HP	9158	1070K	NO	Trigger required
Cadillac	XLR	04-09	62	7001HP	9076	1070K	NO	Trigger required
Cadillac	XT4	19	---	5001	6561	VS20	VS20	Trigger required
Cadillac	XT5	17	---	5001	9773	VS20	VS20	Trigger required
Cadillac	XT5	18-19	---	5001	6561	VS20	VS20	Trigger required
Cadillac	XTS	13-16	---	7001HP-R	9153	VS950	VS950	Trigger required
Cadillac	XTS	17-19	---	7001HP-R	9153	VS20	VS20	Trigger required
Chevrolet	Avalanche	06	62	7003 or 7003A	9107	1070K	NO	Trigger required
Chevrolet	Avalanche	07	62	7001HP	7001HP	2020K	NO	Trigger required
Chevrolet	Avalanche	07	62	7001HP	9158	1070K	NO	Trigger required
Chevrolet	Avalanche	07-13	---	7001HP-R	9153	VS950	VS950	Trigger required
Chevrolet	Aveo	08-11	---	---	9153	VS950	VS950	OBDII required
Chevrolet	Bolt	17-18	---	7001HP-R	9153	VS20	VS20	Trigger required
Chevrolet	Bolt	19	---	---	6164	VS20	VS20	Trigger required
Chevrolet	Camaro	10-15	---	7001HP-R	9153	VS950	VS950	Trigger required
Chevrolet	Camaro	16-19	---	5001	9773	VS20	VS20	Trigger required
Chevrolet	Camaro (sport models)	12-15	62	7001HP	9158	1070K	NO	Trigger required
Chevrolet	Camaro (V8)	16-19	71	5001	9787	2030K	VS40	Trigger required
Chevrolet	Caprice	11-13	62	7001HP	9158	1070K	NO	Trigger required
Chevrolet	Caprice	14-16	71	7001HP	9158	2030K	VS40	Trigger required
Chevrolet	Captiva	12-15	---	7001HP-R	9153	VS950	VS950	Trigger required
Chevrolet	City Express	15-18	50-70	7001HP	9204	2030K	NO	OBDII required
Chevrolet	Cobalt (snap-in)	08-10	---	7001HP-R	9153	VS950	VS950	Trigger required
Chevrolet	Cobalt (clamp-in)	08-'09	71	7001HP	7001HP	1050K	NO	Trigger required
Chevrolet	Cobalt SS	10	62	7001HP	9158	1070K	NO	Trigger required
Chevrolet	Colorado	07-12	62	7003 or 7003A	9131	1110K	NO	Trigger required
Chevrolet	Colorado	15-16	---	7001HP-R	9153	VS950	VS950	Trigger required
Chevrolet	Colorado	17-19	---	7001HP-R	9153	VS20	VS20	Trigger required
Chevrolet	Corvette (C5)	97-00	62	---	8006	1077K	NO	Trigger required
Chevrolet	Corvette (C5)	01-04	62	---	9117	1080K	NO	Trigger required
Chevrolet	Corvette (C6)	05-09	62	7001HP	9076	1070K	NO	Trigger required
Chevrolet	Corvette (C6)	10-13	62	7001HP	9158	1070K	NO	Trigger required
Chevrolet	Corvette (C7)	14-19	71	5001	NEW	2030K	VS40	Auto-relearn

Verify Model Year by checking the 10th digit in the VIN: 8 = 2008MY, 9 = 2009MY, A = 2010MY, B = 2011MY, etc.

Visit [dillvalves.com](http://dillvalves.com) for vehicle look-ups containing parts, pictures, relearns and training videos

Need Additional Help? Call 800-815-3455, option 3 for technical support

# DILL TPMS APPLICATIONS CHART ©

(Row Color designates the required replacement parts kit for the OE sensor.)

Make	Model	Model Year Range	OE Torque In-Lbs	Dill Replacement Sensor	Dill OEM Sensor	Dill Kit	Valve Stem Replacement	Simplified Relearn
Chevrolet	Cruze	11-15	---	7001HP-R	9153	VS950	VS950	Trigger required
Chevrolet	Cruze Limited	16	---	7001HP-R	9153	VS20	VS20	Trigger required
Chevrolet	Cruze	16-18	---	5001	9773	VS20	VS20	Trigger required
Chevrolet	Cruze	19	---	5001	6561	VS20	VS20	Trigger required
Chevrolet	Equinox	07-09	71	7001HP	7001HP	1050K	NO	Trigger required
Chevrolet	Equinox	10-14	---	7001HP-R	9153	VS950	VS950	Trigger required
Chevrolet	Equinox	15-17	---	7001HP-R	9153	VS20	VS20	Trigger required
Chevrolet	Equinox	18-19	---	---	6164	VS20	VS20	Trigger required
Chevrolet	Express Series	08-09	71	7001HP	7001HP	1050K	NO	Trigger required
Chevrolet	Express 1500	10-16	---	7001HP-R	9153	VS950	VS950	Trigger required
Chevrolet	Express 1500	17	---	7001HP-R	9153	VS20	VS20	Trigger required
Chevrolet	Express 2500/3500	10-16	---	7001HP-R	9153	VS950	VS950	Trigger required
Chevrolet	Express 2500/3500	17-19	---	7001HP-R	9153	VS20	VS20	Trigger required
Chevrolet	G Series	08	71	7001HP	7001HP	1050K	NO	Trigger required
Chevrolet	HHR	08-10	62	7001HP	9158	1070K	NO	Trigger required
Chevrolet	HHR	08-11	---	7001HP-R	9153	VS950	VS950	Trigger required
Chevrolet	Impala	06-07	62	7001HP	9158	1070K	NO	Trigger required
Chevrolet	Impala	07-16	---	7001HP-R	9153	VS950	VS950	Trigger required
Chevrolet	Impala (new)	14-15	---	7001HP-R	9153	VS950	VS950	Trigger required
Chevrolet	Impala (new)	16-19	---	7001HP-R	9153	VS20	VS20	Trigger required
Chevrolet	Malibu (clamp-in)	08	71	7001HP	7001HP	1050K	NO	Trigger required
Chevrolet	Malibu	08-15	---	7001HP-R	9153	VS950	VS950	Trigger required
Chevrolet	Malibu (non-turbo)	16	---	7001HP-R	9153	VS20	VS20	Trigger required
Chevrolet	Malibu (turbo or Hybrid)	16-18	---	5001	9773	VS20	VS20	Trigger required
Chevrolet	Malibu	19	---	5001	6561	VS20	VS20	Trigger required
Chevrolet	Monte Carlo	05-07	62	7001HP	9158	1070K	NO	Trigger required
Chevrolet	Monte Carlo	07	---	7001HP-R	9153	VS950	VS950	Trigger required
Chevrolet	Orlando	12-14	---	7001HP-R	9153	VS950	VS950	Trigger required
Chevrolet	Silverado 1500	07-16	---	7001HP-R	9153	VS950	VS950	Trigger required
Chevrolet	Silverado 1500	17	---	7001HP-R	9153	VS20	VS20	Trigger required
Chevrolet	Silverado	18	---	---	6164	VS20	VS20	Trigger required
Chevrolet	Silverado LD (old)	19	---	---	6164	VS20	VS20	Trigger required
Chevrolet	Silverado 1500 (new)	19	---	5001	6561	VS20	VS20	Trigger required
Chevrolet	Silverado 2500/3500	07-16	---	7001HP-R	9153	VS950	VS950	Trigger required
Chevrolet	Silverado 2500/3500	17	---	7001HP-R	9153	VS20	VS20	Trigger required
Chevrolet	Silverado 2500/3500	18-19	---	---	6164	VS20	VS20	Trigger required
Chevrolet	Sonic	12-15	---	7001HP-R	9153	VS950	VS950	Trigger required
Chevrolet	Sonic	16-19	---	7001HP-R	9153	VS20	VS20	Trigger required
Chevrolet	Spark	13-15	---	7001HP-R	9153	VS950	VS950	Trigger required
Chevrolet	Spark	16-19	---	7001HP-R	9153	VS20	VS20	Trigger required
Chevrolet	SS sedan	14	62	7001HP	9158	1070K	NO	Trigger required
Chevrolet	SS sedan	15-17	71	7001HP	9158	2030K	VS40	Trigger required
Chevrolet	Suburban	04	62	---	9115	1070K	NO	Trigger required
Chevrolet	Suburban	05-06	62	7003 or 7003A	9107	1070K	NO	Trigger required
Chevrolet	Suburban 1500	07	62	7001HP	7001HP	2020K	NO	Trigger required
Chevrolet	Suburban 2500	07	62	7001HP	7001HP	2020K	NO	Trigger required
Chevrolet	Suburban 1500	07	62	7001HP	9158	1070K	NO	Trigger required
Chevrolet	Suburban 2500	07	62	7001HP	9158	1070K	NO	Trigger required
Chevrolet	Suburban 1500	07-16	---	7001HP-R	9153	VS950	VS950	Trigger required
Chevrolet	Suburban 2500	07-13	---	7001HP-R	9153	VS950	VS950	Trigger required
Chevrolet	Suburban	17	---	7001HP-R	9153	VS20	VS20	Trigger required
Chevrolet	Suburban	18-19	---	---	6164	VS20	VS20	Trigger required
Chevrolet	Tahoe	04	62	---	9115	1070K	NO	Trigger required
Chevrolet	Tahoe	05-06	62	7003 or 7003A	9107	1070K	NO	Trigger required
Chevrolet	Tahoe	07	62	7001HP	7001HP	2020K	NO	Trigger required
Chevrolet	Tahoe	07	62	7001HP	9158	1070K	NO	Trigger required
Chevrolet	Tahoe	07-17	---	7001HP-R	9153	VS950	VS950	Trigger required
Chevrolet	Tahoe	18-19	---	---	6164	VS20	VS20	Trigger required
Chevrolet	Trailblazer	06-09	62	7001HP	9116	1070K	NO	Trigger required
Chevrolet	Traverse	09-14	---	7001HP-R	9153	VS950	VS950	Trigger required
Chevrolet	Traverse	15-17	---	7001HP-R	9153	VS20	VS20	Trigger required
Chevrolet	Traverse	18-19	---	5001	6561	VS20	VS20	Trigger required
Chevrolet	Trax	15	---	7001HP-R	9153	VS950	VS950	Trigger required
Chevrolet	Trax	16-19	---	7001HP-R	9153	VS20	VS20	Trigger required
Chevrolet	Uplander	08-09	62	7001HP	9158	1070K	NO	Trigger required
Chevrolet	Volt	11-15	---	7001HP-R	9153	VS950	VS950	Trigger required
Chevrolet	Volt	16	---	7001HP-R	9153	VS20	VS20	Trigger required
Chevrolet	Volt	17-18	---	5001	9773	VS20	VS20	Trigger required

\*\* Note: The 1050K is to be used on the Siemens sensors and the 1070K is to be used on the Schrader sensors.

Verify Model Year by checking the 10th digit in the VIN: 8 = 2008MY, 9 = 2009MY, A = 2010MY, B = 2011MY, etc.

Visit [dillvalves.com](http://dillvalves.com) for vehicle look-ups containing parts, pictures, relearns and training videos

Need Additional Help? Call 800-815-3455, option 3 for technical support

# DILL TPMS APPLICATIONS CHART ©

(Row Color designates the required replacement parts kit for the OE sensor.)

Make	Model	Model Year Range	OE Torque In-Lbs	Dill Replacement Sensor	Dill OEM Sensor	Dill Kit	Valve Stem Replacement	Simplified Relearn
Chrysler	200	11-14	71	7001HP	1051	7000K	VS70	Auto-relearn
Chrysler	200 sedan	15-16	---	5001	5775	VS90	VS90	Auto-relearn
Chrysler	200	17	---	5001	5777	VS950	VS950	Auto-relearn
Chrysler	300M	02-04	35	7004	9028	1080K	NO	Trigger required
Chrysler	300	05-07	71	7001HP	1051	1050K	NO	Auto-relearn
Chrysler	300	08	71	7004	1043	1050K	NO	Auto-relearn
Chrysler	300	09	58	5001	9214	9066K	9066K	Auto-relearn
Chrysler	300	10-19	---	5001	9398	VS950	VS950	Auto-relearn
Chrysler	300C SRT8	10-14	58	5001	9214	9066K	9066K	Auto-relearn
Chrysler	Aspen	07-09	58	7001HP	9066	9066K	9066K	Auto-relearn
Chrysler	Crossfire	04-08	35	---	9028	1080K	NO	Dealer OBD only
Chrysler	Pacifica (433 MHz)	04	35	7004	9028	1080K	NO	Trigger required
Chrysler	Pacifica (315 MHz)	04-05	71	7001HP	1052	1050K	NO	Auto-relearn
Chrysler	Pacifica	06-08	71	7001HP	1051	1050K	NO	Auto-relearn
Chrysler	Pacifica	17-19	---	5001	5777	VS950	VS950	Auto-relearn
Chrysler	Prowler	01	62	---	8004	1077K	NO	Dealer OBD only
Chrysler	Prowler	02	35	---	9028	1080K	NO	Dealer OBD only
Chrysler	PT Cruiser	08-10	71	7001HP	1051	1050K	NO	Auto-relearn
Chrysler	Sebring	07-10	71	7001HP	1051	1050K	NO	Auto-relearn
Chrysler	Sebring	10	71	7001HP	1051	7000K	VS70	Auto-relearn
Chrysler	Town and Country	02-03	35	7004	9028	1080K	NO	Trigger required
Chrysler	Town and Country	04-05	71	7001HP	1052	1050K	NO	Auto-relearn
Chrysler	Town and Country	06-07	71	7001HP	1051	1050K	NO	Auto-relearn
Chrysler	Town and Country	08-10	71	7004	1043	1050K	NO	Auto-relearn
Chrysler	Town and Country	10	71	7004	1043	7000K	VS70	Auto-relearn
Chrysler	Town and Country	11-16	---	5001	9398	VS950	VS950	Auto-relearn
Dodge	Avenger	08-10	71	7001HP	1051	1050K	NO	Auto-relearn
Dodge	Avenger	11-14	71	7001HP	1051	7000K	VS70	Auto-relearn
Dodge	Caliber	07-10	71	7001HP	1051	1050K	NO	Auto-relearn
Dodge	Caliber	11-12	71	7001HP	1051	7000K	VS70	Auto-relearn
Dodge	Caravan	04-05	71	7001HP	1052	1050K	NO	Auto-relearn
Dodge	Caravan	06	71	7001HP	1051	1050K	NO	Auto-relearn
Dodge	Challenger SRT8	08-14	58	5001	9214	9066K	9066K	Auto-relearn
Dodge	Challenger	09	58	5001	9214	9066K	9066K	Auto-relearn
Dodge	Challenger	10-19	---	5001	9398	VS950	VS950	Auto-relearn
Dodge	Challenger 6.4L V8	15-19	58	5001	9214	9066K	9066K	Auto-relearn
Dodge	Challenger Hellcat / Demon	15-19	58	5001	9214	9066K	9066K	Auto-relearn
Dodge	Charger	06-07	71	7001HP	1051	1050K	NO	Auto-relearn
Dodge	Charger	08	71	7004	1043	1050K	NO	Auto-relearn
Dodge	Charger	09	58	5001	9214	9066K	9066K	Auto-relearn
Dodge	Charger SRT8	10-14	58	5001	9214	9066K	9066K	Auto-relearn
Dodge	Charger	10-19	---	5001	9398	VS950	VS950	Auto-relearn
Dodge	Charger 6.4L V8	15-19	58	5001	9214	9066K	9066K	Auto-relearn
Dodge	Charger Hellcat	15-19	58	5001	9214	9066K	9066K	Auto-relearn
Dodge	Dakota	08-10	58	7001HP	9154	9066K	9066K	Auto-relearn
Dodge	Dakota	11	---	7001HP-R	9308	VS950	VS950	Auto-relearn
Dodge	Dart	13-16	---	5001	5775	VS90	VS90	Auto-relearn
Dodge	Durango	07-09	58	7001HP	9066	9066K	9066K	Auto-relearn
Dodge	Durango	11-15	---	5001	9398	VS950	VS950	Auto-relearn
Dodge	Durango	16	---	5001	5777	VS90	VS90	Auto-relearn
Dodge	Durango	17-19	---	5001	5777	VS950	VS950	Auto-relearn
Dodge	Durango SRT	18-19	71	5001	2495	7020K	VS70	Auto-relearn
Dodge	Grand Caravan	02-03	35	7004	9028	1080K	NO	Trigger required
Dodge	Grand Caravan	04-05	71	7001HP	1052	1050K	NO	Auto-relearn
Dodge	Grand Caravan	06-07	71	7001HP	1051	1050K	NO	Auto-relearn
Dodge	Grand Caravan	08-10	71	7004	1043	1050K	NO	Auto-relearn
Dodge	Grand Caravan	10	71	7004	1043	7000K	VS70	Auto-relearn
Dodge	Grand Caravan	11-18	---	5001	9398	VS950	VS950	Auto-relearn
Dodge	Journey	09-10	71	7004	1043	1050K	NO	Auto-relearn
Dodge	Journey	11-18	---	5001	9398	VS950	VS950	Auto-relearn
Dodge	Magnum	05-07	71	7001HP	1051	1050K	NO	Auto-relearn
Dodge	Magnum	08	71	7004	1043	1050K	NO	Auto-relearn
Dodge	Nitro	07-09	58	7001HP	9066	9066K	9066K	Auto-relearn
Dodge	Nitro	10-11	---	7001HP-R	9308	VS950	VS950	Auto-relearn
Dodge	Ram C/V	12-15	---	5001	9398	VS950	VS950	Auto-relearn
Dodge	Ram Promaster	14-18	71	5001	9214	1100K	VS40	Auto-relearn
Dodge	Ram Promaster City	15-18	71	5001	9214	1100K	VS40	Auto-relearn
Dodge	Ram 1500	08	58	9154	9154	9066K	9066K	Auto-relearn
Dodge	Ram 1500 (Siemens)	09	71	7004	1043	1050K	NO	Auto-relearn

Verify Model Year by checking the 10th digit in the VIN: 8 = 2008MY, 9 = 2009MY, A = 2010MY, B = 2011MY, etc.

Visit [dillvalves.com](http://dillvalves.com) for vehicle look-ups containing parts, pictures, relearns and training videos

Need Additional Help? Call 800-815-3455, option 3 for technical support

# DILL TPMS APPLICATIONS CHART ©

(Row Color designates the required replacement parts kit for the OE sensor.)

Make	Model	Model Year Range	OE Torque In-Lbs	Dill Replacement Sensor	Dill OEM Sensor	Dill Kit	Valve Stem Replacement	Simplified Relearn
Dodge	Ram 1500 (Schrader)	09	58	7004	1043	9066K	9066K	Auto-relearn
Dodge	Ram 2500	08-09	58	7001HP	9154	9066K	9066K	Auto-relearn
Dodge	Ram	10-13	---	5001	9398	VS950	VS950	Auto-relearn
Dodge	Ram 1500, 2500, 3500 SRW	14-18	---	5001	6815	VS65	VS65	Auto-relearn
Dodge	Ram 1500 Classic (DS)	19	---	5001	6815	VS65	VS65	Auto-relearn
Dodge	Ram 1500 (DT)	19	---		3199	VS950	VS950	Auto-relearn
Dodge	Ram 3500 Dually (Outer Steel Wheel Sensor)	14-18	---	5001	6815	VS65	VS65	Auto-relearn
Dodge	Ram 3500 Dually (Outer Alloy Wheel Sensor)	14-18	80-125	5001	6829	VS35	VS35	Auto-relearn
Dodge	Ram 3500 Dually (Inner Rear Wheel Sensor)	14-18	---	5001	6825	VS65	VS65	Auto-relearn
Dodge	Sprinter	07-10	54	7003 or 7003A*	1042	1098K	1098K	Trigger required'
Dodge	Viper	03-10	35		9028	1080K	NO	Dealer OBD only
Dodge	SRT Viper	13-17	58	5001	9214	9066K	9066K	Auto-relearn
* Note: 7003A must be scanned while pressurized before the vehicle is driven.								
Ferrari	F430	05-07	35		9001	1090K	1092	No tools needed
Ferrari	F430 (Post July 2007)	07-09	35		9011	1090K	1092	No tools needed
Ferrari	458	10-15	40		9011	1096	1096	No tools needed
Ferrari	488	16-17	40		9011	1096	1096	No tools needed
Ferrari	575M (433 MHz)	02-05	35		9001	1090K	1092	No tools needed
Ferrari	575M (315 MHz)	02-05	35		9004	1090K	1092	No tools needed
Ferrari	599	07-11	35		9001	1090K	1092	No tools needed
Ferrari	612 Scaglinetta	05-10	35		9001	1090K	1092	No tools needed
Ferrari	California	09-10	35		9011	1090K	1092	No tools needed
Ferrari	California	11-17	40		9011	1096	1096	No tools needed
Ferrari	Enzo	03-05	35		9005	1090K	1092	No tools needed
Ferrari	F12	13-17	40		9011	1096	1096	No tools needed
Ferrari	FF	12-16	40		9011	1096	1096	No tools needed
Ferrari	FXX	05-06	35		9005	1090K	1092	No tools needed
Ferrari	LaFerrari	14-15	40		9011	1096	1096	No tools needed
Fiat	124 Spider Abarth	17-19	71	7001HP	1056	7020K	VS70	Auto-relearn
Fiat	500	12-18	---	5001	9398	VS950	VS950	Auto-relearn
Fiat	500L	14-19	---	5001	9398	VS950	VS950	Auto-relearn
Fiat	500X	16-17	---	5001	5775	VS90	VS90	Auto-relearn
Fiat	500X	18	---	5001	5777	VS950	VS950	Auto-relearn
Ford	C-Max	13-18	---	7001HP-R	9315	VS950	VS950	Trigger required
Ford	Crown Victoria	08-11	---	7001HP-R	1048	Banded	NO	Trigger required
Ford	E Series	08-09	---	7001HP-R	1048-HP	Banded	NO	Trigger required
Ford	E-250 / E-350 van	08-09	---	7001HP-R	1048-HP	Banded	NO	Trigger required
Ford	E Series	10-14	---	7001HP-R	9315	VS950	VS950	Trigger required
Ford	E Series	16-19	---	7001HP-R	9315	VS950	VS950	Trigger required
Ford	EcoSport	18-19	---	7003A	9280	VS20	VS20	Auto-relearn
Ford	Edge	07-10	---	7001HP-R	1048	Banded	NO	Trigger required
Ford	Edge	11-14	---	7001HP-R	9315	VS950	VS950	Trigger required
Ford	Edge	15-19	---	7003A	9280	VS20	VS20	Auto-relearn
Ford	Escape	05-08	---	7001HP-R	1048	Banded	NO	Trigger required
Ford	Escape	09-19	---	7001HP-R	9315	VS950	VS950	Trigger required
Ford	Expedition	03-04	44	7004**	9096	1060K	NO	Trigger required
Ford	Expedition	05-06	44	7001HP**	9135	1060K	NO	Trigger required
Ford	Expedition	07-10	---	7001HP-R	1048	Banded	NO	Trigger required
Ford	Expedition	11-17	---	7001HP-R	9315	VS950	VS950	Trigger required
Ford	Expedition	18	---	7003A	9280	VS20	VS20	Auto-relearn
Ford	Explorer	02-05	44	7004**	9096	1060K	NO	Trigger required
Ford	Explorer Sport Trac	07-10	---	7001HP-R	1048	Banded	NO	Trigger required
Ford	Explorer	06-10	---	7001HP-R	1048	Banded	NO	Trigger required
Ford	Explorer	11-15	---	7001HP-R	9315	VS950	VS950	Trigger required
Ford	Explorer	16-19	---	7003A	9280	VS20	VS20	Auto-relearn
Ford	F-150 (Light Duty)	07-08	---	7001HP-R	1048	Banded	NO	Trigger required
Ford	F-150 (Heavy Duty)	07-08	---	7001HP-R	1048-HP	Banded	NO	Trigger required
Ford	F-150	09-14	---	7001HP-R	9315	VS950	VS950	Trigger required
Ford	F-150	15-19	---	7003A	9280	VS20	VS20	Auto-relearn
Ford	F-250 / F-350	08-09	---	7001HP-R	1048-HP	Banded	NO	Trigger required
Ford	F-250 / F-350	10-16	---	7001HP-R	9315	VS950	VS950	Trigger required
Ford	F-250 / F-350 (snap-in)	17-19	---	7003A	9280	VS20	VS20	Auto-relearn
Ford	F-350 Dually (clamp-in)	17-19	35	7003A	9291	VS241	VS241	Trigger required
Ford	Fiesta	11-19	---	7001HP-R	9315	VS950	VS950	Trigger required
Ford	Flex	09-10	---	7001HP-R	1048	Banded	NO	Trigger required
Ford	Flex	11-19	---	7001HP-R	9315	VS950	VS950	Trigger required

Verify Model Year by checking the 10th digit in the VIN: 8 = 2008MY, 9 = 2009MY, A = 2010MY, B = 2011MY, etc.

Visit [dillvalves.com](http://dillvalves.com) for vehicle look-ups containing parts, pictures, relearns and training videos

Need Additional Help? Call 800-815-3455, option 3 for technical support

# DILL TPMS APPLICATIONS CHART ©

(Row Color designates the required replacement parts kit for the OE sensor.)

Make	Model	Model Year Range	OE Torque In-Lbs	Dill Replacement Sensor	Dill OEM Sensor	Dill Kit	Valve Stem Replacement	Simplified Relearn
Ford	Focus	08-09	---	7001HP-R	1048	Banded	NO	Trigger required
Ford	Focus (non-RS)	10-18	---	7001HP-R	9315	VS950	VS950	Trigger required
Ford	Focus RS (clamp-in)	16-18	35	7003A	9291	VS240MC	VS240MC	Auto-relearn
Ford	Focus RS (snap-in)	16-18	---	7003A	9280	VS20	VS20	Auto-relearn
Ford	Freestar	06-07	---	7001HP-R	1048	Banded	NO	Trigger required
Ford	Fusion	08-09	---	7001HP-R	1048	Banded	NO	Trigger required
Ford	Fusion	10-16	---	7001HP-R	9315	VS950	VS950	Trigger required
Ford	Fusion	17-19	---	7003A	9280	VS20	VS20	Auto-relearn
Ford	GT	17	35	7003A	9291	VS240MC	VS240MC	Auto-relearn
Ford	Mustang	07-09	---	7001HP-R	1048	Banded	NO	Trigger required
Ford	Mustang	10-14	---	7001HP-R	9315	VS950	VS950	Trigger required
Ford	Mustang	15-19	---	7003A	9280	VS20	VS20	Auto-relearn
Ford	Mustang (Shelby)	15-19	35	7003A	9291	VS240MC	VS240MC	Auto-relearn
Ford	Police Interceptor sedan	13-19	---	7001HP-R	9315	VS950	VS950	Trigger required
Ford	Police Interceptor Utility	13-15	---	7001HP-R	9315	VS950	VS950	Trigger required
Ford	Police Interceptor Utility	16-19	---	7003A	9280	VS20	VS20	Auto-relearn
Ford	Ranger	07-11	---	7001HP-R	1048	Banded	NO	Trigger required
Ford	Shelby GT	13-14	35	7001HP	9315	VS925C	VS925C	Trigger required
Ford	Super Duty	08-09	---	7001HP-R	1048-HP	Banded	NO	Trigger required
Ford	Super Duty	10-16	---	7001HP-R	9315	VS950	VS950	Trigger required
Ford	Super Duty (snap-in)	17-19	---	7003A	9280	VS20	VS20	Auto-relearn
Ford	Super Duty (clamp-in)	17-19	35	7003A	9291	VS241	VS241	Trigger required
Ford	Super Duty Trailer TPMS	17-18	35		NEW	VS240MC	VS240MC	Trigger required
Ford	Taurus	08-10	---	7001HP-R	1048	Banded	NO	Trigger required
Ford	Taurus	11-19	---	7001HP-R	9315	VS950	VS950	Trigger required
Ford	Taurus X	08-09	---	7001HP-R	1048	Banded	NO	Trigger required
Ford	Transit Connect	10-18	---	7001HP-R	9315	VS950	VS950	Trigger required
Ford	Transit Connect	19	---	7003A	9280	VS20	VS20	
Ford	Transit (SRW)	15-19	---	7001HP-R	9315	VS950	VS950	Trigger required
** Note: Redi-Sensor relearn must be performed with a scan tool, not a magnet.								
Freightliner	Sprinter	07-13	54	7003 or 7003A*	1042	1098K	1098K	Trigger required*
Freightliner	Sprinter	14-16	53	5001	9214	2030K	9066K	No tools needed
* Note: 7003A must be scanned while pressurized before the vehicle is driven.								
Genesis	G70	18	---		NEW	VS20	VS20	OBDII required
Genesis	G80	17	71	5001	5510	7020K	VS70	OBDII required
Genesis	G80	18-19	71	5001	5510	7020K	VS70	OBDII required
Genesis	G90	17-18	71	5001	5523	7020K	VS70	OBDII required
GMC	Acadia	07-08	71	7001HP	7001HP	1050K	NO	Trigger required
GMC	Acadia	09-14	---	7001HP-R	9153	VS950	VS950	Trigger required
GMC	Acadia	15-16	---	7001HP-R	9153	VS20	VS20	Trigger required
GMC	Acadia Limited	17	---	7001HP-R	9153	VS20	VS20	Trigger required
GMC	Acadia	17	---	5001	9773	VS20	VS20	Trigger required
GMC	Acadia	18-19	---	5001	6561	VS20	VS20	Trigger required
GMC	Canyon	07-12	62	7003 or 7003A	9131	1110K	NO	Trigger required
GMC	Canyon	15-16	---	7001HP-R	9153	VS950	VS950	Trigger required
GMC	Canyon	17-19	---	7001HP-R	9153	VS20	VS20	Trigger required
GMC	Envoy	06-09	62	7001HP	9116	1070K	NO	Trigger required
GMC	Savana	08-09	71	7001HP	7001HP	1050K	NO	Trigger required
GMC	Savana	10-16	---	7001HP-R	9153	VS950	VS950	Trigger required
GMC	Savana	17-18	---	7001HP-R	9153	VS20	VS20	Trigger required
GMC	Sierra 1500	07-16	---	7001HP-R	9153	VS950	VS950	Trigger required
GMC	Sierra 1500	17	---	7001HP-R	9153	VS20	VS20	Trigger required
GMC	Sierra	18	---		6164	VS20	VS20	Trigger required
GMC	Sierra Limited (old)	19	---		6164	VS20	VS20	Trigger required
GMC	Sierra 1500 (new)	19	---	5001	6561	VS20	VS20	Trigger required
GMC	Sierra 2500/3500	07-16	---	7001HP-R	9153	VS950	VS950	Trigger required
GMC	Sierra 2500/3500	17	---	7001HP-R	9153	VS20	VS20	Trigger required
GMC	Sierra 2500/3500	18-19	---		6164	VS20	VS20	Trigger required
GMC	Terrain	10-14	---	7001HP-R	9153	VS950	VS950	Trigger required
GMC	Terrain	15-17	---	7001HP-R	9153	VS20	VS20	Trigger required
GMC	Terrain	18-19	---		6164	VS20	VS20	Trigger required
GMC	Yukon (all)	04	62		9115	1070K	NO	Trigger required
GMC	Yukon (all)	05-06	62	7003 or 7003A	9107	1070K	NO	Trigger required
GMC	Yukon	07	62	7001HP	7001HP	2020K	NO	Trigger required
GMC	Yukon	07	62	7001HP	9158	1070K	NO	Trigger required
GMC	Yukon 2500	07	62	7001HP	7001HP	2020K	NO	Trigger required
GMC	Yukon 2500	07	62	7001HP	9158	1070K	NO	Trigger required
GMC	Yukon	07-16	---	7001HP-R	9153	VS950	VS950	Trigger required
GMC	Yukon 2500	07-13	---	7001HP-R	9153	VS950	VS950	Trigger required

Verify Model Year by checking the 10th digit in the VIN: 8 = 2008MY, 9 = 2009MY, A = 2010MY, B = 2011MY, etc.

Visit [dillvalves.com](http://dillvalves.com) for vehicle look-ups containing parts, pictures, relearns and training videos

Need Additional Help? Call 800-815-3455, option 3 for technical support

# DILL TPMS APPLICATIONS CHART ©

(Row Color designates the required replacement parts kit for the OE sensor.)

Make	Model	Model Year Range	OE Torque In-Lbs	Dill Replacement Sensor	Dill OEM Sensor	Dill Kit	Valve Stem Replacement	Simplified Relearn
GMC	Yukon	17	---	7001HP-R	9153	VS20	VS20	Trigger required
GMC	Yukon	18-19	---		6164	VS20	VS20	Trigger required
Honda	Accord	08-12	35	7002 or 7002A	1208	1100K	NO	OBDII required
Honda	Civic	08-14	35	7002 or 7002A	1212	2045K	NO	OBDII required
Honda	CR-V	07-11	35	7002 or 7002A	1208	1100K	NO	OBDII required
Honda	CR-V	12-13	71	7002 or 7002A	5511	7020K	VS70	OBDII required
Honda	CR-Z	11-15	35	7002 or 7002A	1212	2045K	NO	OBDII required
Honda	Crosstour	10-15	71	7002 or 7002A	5511	7020K	VS70	OBDII required
Honda	Element	07-08	40	7002 or 7002A	1058	2000K	1096	OBDII required
Honda	Element	09-11	35	7002 or 7002A	1212	2045K	NO	OBDII required
Honda	Fit	08	35	7002 or 7002A	1208	1100K	NO	OBDII required
Honda	Fit	09-14	35	7002 or 7002A	1212	2045K	NO	OBDII required
Honda	Insight	10-14	35	7002 or 7002A	1212	2045K	NO	OBDII required
Honda	Odyssey EX, EX-L, LX	07	40	7002 or 7002A	1058	2000K	1096	OBDII required
Honda	Odyssey EX, EX-L, LX	08-10	40	7002 or 7002A	1058	2045K or 2000K	None or 1096	OBDII required
Honda	Odyssey Touring	05-07	40	7002A	1057	2000K	1096	Auto-relearn
Honda	Odyssey Touring	08-10	40	7002A	1057	2045K or 2000K	None or 1096	Auto-relearn
Honda	Odyssey and Touring	11-17	35	7002 or 7002A	1212	2045K	NO	OBDII required
Honda	Odyssey	18-19	71		3751	7000K	VS70	Auto-relearn
Honda	Pilot (Steel Wheels)	05-08	40	7002A	1059	2000K	1097	Auto-relearn
Honda	Pilot (Alloy Wheels)	05-08	40	7002A	1057	2000K	1096	Auto-relearn
Honda	Pilot (Alloy Wheels)	09-15	35	7002A	1209	1100K	NO	Auto-relearn
Honda	Pilot (Steel Wheels)	09-15	35	7002A	1219	1100K	NO	Auto-relearn
Honda	Pilot	16-19	71		3751	7000K	VS70	Auto-relearn
Honda	Ridgeline (Steel Wheels)	06-08	40	7002A	1059	2000K	1097	Auto-relearn
Honda	Ridgeline (Alloy Wheels)	06-08	40	7002A	1057	2000K	1096	Auto-relearn
Honda	Ridgeline	09-14	40	7002A	1057	2045K or 2000K	None or 1096	Auto-relearn
Honda	Ridgeline	17-19	71		3751	7000K	VS70	Auto-relearn
Honda	S2000	08-09	35	7002 or 7002A	1208	1100K	NO	OBDII required
Hummer	H2	08-09	---	7001HP-R	9153	VS950	VS950	Trigger required
Hummer	H3	06-10	62	7003 or 7003A	9131	1110K	NO	Trigger required
Hummer	H3T	09-10	62	7003 or 7003A	9131	1110K	NO	Trigger required
Hyundai	Accent	08-11	31-40	7002, 7002A, or 1206A	1029	2040K	NO	OBDII required
Hyundai	Accent	12-13	71	7001HP	5507	7020K	VS70	OBDII required
Hyundai	Accent	14	71	7003A	5508	7020K	VS70	OBDII required
Hyundai	Accent	15-17	71	5001	5510	7020K	VS70	OBDII required
Hyundai	Accent	18-19	71	5001	5510	7020K	VS70	OBDII required
Hyundai	Azera	07-11	40	7002 or 7002A	1068	2000K	1096	OBDII required
Hyundai	Azera	12-14	35		1233	2040K	VS965	OBDII required
Hyundai	Azera	15-17	35	5001	NEW	2040K	VS965	OBDII required
Hyundai	Elantra	08-10	40	7002 or 7002A	1068	2000K	1096	OBDII required
Hyundai	Elantra	11-13	35	7002 or 7002A	1222	2040K	VS965	OBDII required
Hyundai	Elantra (Post Nov. 2013)	14-16	35		3205	2040K	VS965	OBDII required
Hyundai	Elantra	17-19	71	5001	5523	7020K	VS70	OBDII required
Hyundai	Elantra Touring	09-12	71	7001HP	5507	1050K or 7020K	None or VS70	Auto-relearn
Hyundai	Elantra GT	13-17	71	7003A	5508	7020K	VS70	OBDII required
Hyundai	Elantra GT	18	71	5001	5523	7020K	VS70	OBDII required
Hyundai	Entourage	07-09	40		1028	2000K	1096	OBDII required
Hyundai	Equus	11-13	31-40	7002A	1029	2040K	NO	OBDII required
Hyundai	Equus	14-16	71	7003A	5508	7020K	VS70	OBDII required
Hyundai	Genesis Sedan	09-13	31-40	7002A	1029	2040K	NO	OBDII required
Hyundai	Genesis Sedan	14-16	71	5001	5510	7020K	VS70	OBDII required
Hyundai	Genesis Coupe	10-12	71	7001HP	5507	7020K	VS70	OBDII required
Hyundai	Genesis Coupe	13-16	71	7003A	5508	7020K	VS70	OBDII required
Hyundai	Genesis G70	18	---		NEW	VS20	VS20	OBDII required
Hyundai	Genesis G80	17	71	5001	5510	7020K	VS70	OBDII required
Hyundai	Genesis G80	18	71	5001	5510	7020K	VS70	OBDII required
Hyundai	Genesis G90	17-18	71	5001	5523	7020K	VS70	OBDII required
Hyundai	Ioniq	17-19	71	5001	5523	7020K	VS70	OBDII required
Hyundai	Kona	18-19	71	5001	5523	7020K	VS70	OBDII required
Hyundai	Santa Fe	07-08	40		1028	2000K	1096	OBDII required
Hyundai	Santa Fe	09	40	7002 or 7002A	1068	2000K	1096	OBDII required
Hyundai	Santa Fe	10-12	11	7002 or 7002A	1068	VS1010	VS1010	OBDII required
Hyundai	Santa Fe	13-18	71	7003A	5508	7020K	VS70	OBDII required

Verify Model Year by checking the 10th digit in the VIN: 8 = 2008MY, 9 = 2009MY, A = 2010MY, B = 2011MY, etc.

Visit [dillvalves.com](http://dillvalves.com) for vehicle look-ups containing parts, pictures, relearns and training videos

Need Additional Help? Call 800-815-3455, option 3 for technical support



**DILL TPMS APPLICATIONS CHART ©**

(Row Color designates the required replacement parts kit for the OE sensor.)

Make	Model	Model Year Range	OE Torque In-Lbs	Dill Replacement Sensor	Dill OEM Sensor	Dill Kit	Valve Stem Replacement	Simplified Relearn
Hyundai	Santa Fe Sport	18	71	5001	5523	7020K	VS70	OBDII required
Hyundai	Santa Fe XL	19	71	7003A	5508	7020K	VS70	OBDII required
Hyundai	Santa Fe (non-XL)	19	---	5001	9237	VS20	VS20	OBDII required
Hyundai	Sonata	07	40	7002A	1058	2000K	1096	OBDII required
Hyundai	Sonata GLS/Limited	08	40	7002A	1058	2000K	1096	OBDII required
Hyundai	Sonata SE	08	31-40	7002, 7002A, or 1206A	1029	2040K	NO	OBDII required
Hyundai	Sonata	09-10	31-40	7002, 7002A, or 1206A	1029	2040K	NO	OBDII required
Hyundai	Sonata	11-12	71	7001HP	5507	7020K	VS70	OBDII required
Hyundai	Sonata	13-14	71	7003A	5508	7020K	VS70	OBDII required
Hyundai	Sonata Hybrid	15	71	7003A	5508	7020K	VS70	OBDII required
Hyundai	Sonata (non-hybrid)	15	---	5001	9237	VS20	VS20	OBDII required
Hyundai	Sonata & Hybrid	16-19	---	5001	9237	VS20	VS20	OBDII required
Hyundai	Tiburon	07-08	40	7002A	1058	2000K	1096	OBDII required
Hyundai	Tucson	06-07	40	7002A	1058	2000K	1096	OBDII required
Hyundai	Tucson	08-10	40	7002A	1058	2000K	1096	OBDII required
Hyundai	Tucson	10-13	31-40	7002, 7002A, or 1206A	1029	2040K	NO	OBDII required
Hyundai	Tucson	14-15	35		2510	2040K	VS965	OBDII required
Hyundai	Tucson	16-19	---	5001	9237	VS20	VS20	OBDII required
Hyundai	Veloster	12-17	---		9505	VS950	VS950	OBDII required
Hyundai	Veloster	19	71	5001	5523	7020K	VS70	OBDII required
Hyundai	Veracruz	07-08	40		1028	2000K	1096	OBDII required
Hyundai	Veracruz	09-12	40	7002 or 7002A	1068	2000K	1096	OBDII required
Infiniti	EX	08-10	35	7001HP	9204	1100K	NO	OBDII required
Infiniti	EX	11-13	35	7003 or 7003A	1216	1100K	NO	OBDII required
Infiniti	FX	03-07	45-60	7001HP	9064	1080K	NO	OBDII required
Infiniti	FX (Post June 2007)	08	66	7001HP	9204	2030K	NO	OBDII required
Infiniti	FX (Post June 2008)	09-10	35	7001HP	9204	1100K	NO	OBDII required
Infiniti	FX (Post March 2010)	10-13	35	7003 or 7003A	1216	1100K	NO	OBDII required
Infiniti	G35	04-07	45-60	7001HP	9064	1080K	NO	OBDII required
Infiniti	G35 Coupe (Post Aug. 2006)	07	66	7001HP	9204	2030K	NO	OBDII required
Infiniti	G35 Sedan	07	35	7001HP	9204	1100K	NO	OBDII required
Infiniti	G	08-10	35	7001HP	9204	1100K	NO	OBDII required
Infiniti	G (Post March 2010)	10-13	35	7003 or 7003A	1216	1100K	NO	OBDII required
Infiniti	JX	13	71		5556	7020K	VS70	OBDII required
Infiniti	M	03-07	45-60	7001HP	9064	1080K	NO	OBDII required
Infiniti	M	08-10	66	7001HP	9204	2030K	NO	OBDII required
Infiniti	M (Post March 2010)	10-13	35	7003 or 7003A	1216	1100K	NO	OBDII required
Infiniti	Q45	03-06	45-60	7001HP	9064	1080K	NO	OBDII required
Infiniti	Q40	15	35	7003 or 7003A	1216	1100K	NO	OBDII required
Infiniti	Q50	14-15	71		5556	7020K	VS70	OBDII required
Infiniti	Q50	16-19	71		5556	7020K	VS70	OBDII required
Infiniti	Q60	14-15	35	7003 or 7003A	1216	1100K	NO	OBDII required
Infiniti	Q60	17-18	71		5556	7020K	VS70	OBDII required
Infiniti	Q70	14-19	35	7003 or 7003A	1216	1100K	NO	OBDII required
Infiniti	QX30	17-18	71	5001	9214	1100K	VS40	No tools needed
Infiniti	QX50	14-17	35	7003 or 7003A	1216	1100K	NO	OBDII required
Infiniti	QX50	19	---		5661	VS90	VS90	OBDII required
Infiniti	QX56	04-07	49	7001HP	9161	1080K	NO	OBDII required
Infiniti	QX56	08-10	66	7001HP	9204	2030K	NO	OBDII required
Infiniti	QX56 (Post March 2010)	10	35	7003 or 7003A	1216	1100K	NO	OBDII required
Infiniti	QX56	11-13	35	7003A	1216	1100K	NO	OBDII required
Infiniti	QX60	14-19	71		5556	7020K	VS70	OBDII required
Infiniti	QX70	14	35	7003 or 7003A	1216	1100K	NO	OBDII required
Infiniti	QX70	15-17	35	7003 or 7003A	1216	1100K	NO	OBDII required
Infiniti	QX80	14-16	35	7003A	1216	1100K	NO	OBDII required
Infiniti	QX80	17	35	5001	1382	1100K	NO	OBDII required
Infiniti	QX80	18-19	35		1375	1100K	NO	OBDII required
ITEC	Trucks(433 Mhz)	all	---		9010	VS9013 or VS9980	VS9013 or VS9980	
Isuzu	Ascender	06-08	62	7001HP	9116	1070K	NO	Trigger required
Isuzu	I-290	07-08	62	7003 or 7003A	9131	1110K	NO	Trigger required
Isuzu	I-370	07-08	62	7003 or 7003A	9131	1110K	NO	Trigger required
Isuzu	Rodeo	04	35		9028	1080K	NO	Dealer OBD only
Jaguar	E-Pace	18	71	5001	5276	7020K	VS70	Auto-relearn
Jaguar	F-Pace	17-19	71	5001	5276	7020K	VS70	Auto-relearn
Jaguar	F-Type (315MHz)	14-15	71		1045	7020K	VS70	Auto-relearn

Verify Model Year by checking the 10th digit in the VIN: 8 = 2008MY, 9 = 2009MY, A = 2010MY, B = 2011MY, etc.

Visit [dillvalves.com](http://dillvalves.com) for vehicle look-ups containing parts, pictures, relearns and training videos

Need Additional Help? Call 800-815-3455, option 3 for technical support

# DILL TPMS APPLICATIONS CHART ©

(Row Color designates the required replacement parts kit for the OE sensor.)

Make	Model	Model Year Range	OE Torque In-Lbs	Dill Replacement Sensor	Dill OEM Sensor	Dill Kit	Valve Stem Replacement	Simplified Relearn
Jaguar	F-Type (433MHz Export)	14	71		1046	1050K	NO	Auto-relearn
Jaguar	F-Type (433MHz)	15-19	71	5001	5276	7020K	VS70	Auto-relearn
Jaguar	Super V8 (315MHz)	05-09	71		1055	1050K	NO	Auto-relearn
Jaguar	Super V8 (433MHz Export)	05-09	71		1046	1050K	NO	Auto-relearn
Jaguar	Vanden Plas (315MHz)	04-09	71		1055	1050K	NO	Auto-relearn
Jaguar	Vanden Plas (433MHz Export)	04-09	71		1046	1050K	NO	Auto-relearn
Jaguar	X-Type (315MHz)	08	71		1055	1050K	NO	Auto-relearn
Jaguar	X-Type (433MHz Export)	08	71		1046	1050K	NO	Auto-relearn
Jaguar	XE	17-18	71	5001	5276	7020K	VS70	Auto-relearn
Jaguar	XF (315MHz)	09-16	71		1055	1050K	NO	Auto-relearn
Jaguar	XF (433MHz Export)	09-15	71		1046	1050K	NO	Auto-relearn
Jaguar	XF (433MHz)	16-18	71	5001	5276	7020K	VS70	Auto-relearn
Jaguar	XJ (315MHz)	06-09	71		1055	1050K	NO	Auto-relearn
Jaguar	XJ (315MHz)	10-11	71		1045	1050K	NO	Auto-relearn
Jaguar	XJ (433MHz Export)	06-11	71		1046	1050K	NO	Auto-relearn
Jaguar	XJ (315MHz)	12-16	71		1045	1050K or 7020K	None or VS70	Auto-relearn
Jaguar	XJ (433MHz Export)	12-14	71		1046	1050K	NO	Auto-relearn
Jaguar	XJ (433MHz)	15-18	71	5001	5276	7020K	VS70	Auto-relearn
Jaguar	XK (315MHz)	07-15	71		1055	1050K	NO	Auto-relearn
Jaguar	XK (433MHz Export)	07-15	71		1046	1050K	NO	Auto-relearn
Jeep	Cherokee	14-18	---	5001	6815	VS65	VS65	Auto-relearn
Jeep	Cherokee	19	---		NEW	VS65	VS65	Auto-relearn
Jeep	Commander	06	71	7001HP	1051	1050K	NO	Auto-relearn
Jeep	Commander	07	58	7001HP	9066	9066K	9066K	Auto-relearn
Jeep	Commander	08-10	58	7004	1043	9066K	9066K	Auto-relearn
Jeep	Compass	07-10	71	7001HP	1051	1050K	NO	Auto-relearn
Jeep	Compass	11-12	71	7001HP	1051	7000K	VS70	Auto-relearn
Jeep	Compass (315MHz)	13-17	---	7001HP-R	9308	VS950	VS950	Auto-relearn
Jeep	Compass (433MHz Export)	13-14	---	5001	9481	VS950	VS950	Auto-relearn
Jeep	Compass (Next Gen)	17-18	---	5001	5777	VS950	VS950	Auto-relearn
Jeep	Grand Cherokee	02-04	64	7004	9028	1080K	NO	Trigger required
Jeep	Grand Cherokee	05-06	71	7001HP	1051	1050K	NO	Auto-relearn
Jeep	Grand Cherokee	07	58	7001HP	9066	9066K	9066K	Auto-relearn
Jeep	Grand Cherokee	08-10	58	7004	1043	9066K	9066K	Auto-relearn
Jeep	Grand Cherokee	11-15	---	5001	9398	VS950	VS950	Auto-relearn
Jeep	Grand Cherokee	16	---	5001	5777	VS90	VS90	Auto-relearn
Jeep	Grand Cherokee	17-19	---	5001	5777	VS950	VS950	Auto-relearn
Jeep	Grand Cherokee SRT8	12-15	58	5001	9214	9066K	9066K	Auto-relearn
Jeep	Grand Cherokee SRT	16-18	71	5001	2495	7020K	VS70	Auto-relearn
Jeep	Liberty	04	64	7004	9028	1080K	NO	Trigger required
Jeep	Liberty	05-06	71	7001HP	1051	1050K	NO	Auto-relearn
Jeep	Liberty	07-10	58	7001HP	9066	9066K	9066K	Auto-relearn
Jeep	Liberty	10-12	---	7001HP-R	9308	VS950	VS950	Auto-relearn
Jeep	Liberty (433MHz Export)	07-09	58	7004	1043	9066K	9066K	Auto-relearn
Jeep	Liberty (433MHz Export)	10-12	---	5001	9481	VS950	VS950	Auto-relearn
Jeep	Patriot	07-10	71	7001HP	1051	1050K	NO	Auto-relearn
Jeep	Patriot	11-12	71	7001HP	1051	7000K	VS70	Auto-relearn
Jeep	Patriot	13-17	---	7001HP-R	9308	VS950	VS950	Auto-relearn
Jeep	Patriot (433MHz Export)	12-14	---	5001	9481	VS950	VS950	Auto-relearn
Jeep	Renegade	15-16	---	5001	5775	VS90	VS90	Auto-relearn
Jeep	Renegade	17-18	---	5001	5777	VS950	VS950	Auto-relearn
Jeep	Wrangler	07-10	58	7001HP	9066	9066K	9066K	Auto-relearn
Jeep	Wrangler (433MHz Export)	08-10	58	7004	1043	9066K	9066K	Auto-relearn
Jeep	Wrangler	10-12	---	7001HP-R	9308	VS950	VS950	Auto-relearn
Jeep	Wrangler (433MHz Export)	10-12	---		9481	VS950	VS950	Auto-relearn
Jeep	Wrangler (JK)	13-18	---	5001	9398	VS950	VS950	Auto-relearn
Jeep	Wrangler (JL)	18-19	---	5001	9398	VS950	VS950	Auto-relearn
** Note: The 1050K is to be used on the Siemens sensors and the 9066K or 2030K is to be used on the Schrader sensors.								
KIA	Amanti	07-08	40	7002A	1058	2000K	1096	OBDII required
KIA	Amanti	09	40	7002A	1058	2000K	1096	OBDII required
KIA	Borrego	09-11	31-40	7002, 7002A, or 1206A	1029	2040K	NO	OBDII required
KIA	Cadenza	14-16	71	7003A	5508	7020K	VS70	OBDII required
KIA	Cadenza	17-18	71	5001	5523	7020K	VS70	OBDII required
KIA	Forte	10-13	71	7001HP	5507	7020K	VS70	OBDII required
KIA	Forte	14-15	35		2510	2040K	VS965	OBDII required
KIA	Forte	16-18	35		3205	2040K	VS965	OBDII required
KIA	K900	15-17	---		NEW	VS950	VS950	OBDII required

Verify Model Year by checking the 10th digit in the VIN: 8 = 2008MY, 9 = 2009MY, A = 2010MY, B = 2011MY, etc.

Visit [dillvalves.com](http://dillvalves.com) for vehicle look-ups containing parts, pictures, relearns and training videos

Need Additional Help? Call 800-815-3455, option 3 for technical support

(Row Color designates the required replacement parts kit for the OE sensor.)

Make	Model	Model Year Range	OE Torque In-Lbs	Dill Replacement Sensor	Dill OEM Sensor	Dill Kit	Valve Stem Replacement	Simplified Relearn
KIA	K900	19	---		9237	VS20	VS20	
KIA	Magentis	08-10	40	7002 or 7002A	1068	2000K	1096	OBDII required
KIA	Niro	17-19	71	5001	5523	7020K	VS70	OBDII required
KIA	Optima	06-10	40	7002 or 7002A	1068	2000K	1096	OBDII required
KIA	Optima	11-13	71	7001HP	5507	7020K	VS70	OBDII required
KIA	Optima	14-15	71	7003A	5508	7020K	VS70	OBDII required
KIA	Optima Hybrid	16	71	7003A	5508	7020K	VS70	OBDII required
KIA	Optima non-hybrid	16	71	5001	5523	7020K	VS70	OBDII required
KIA	Optima	17-19	71	5001	5523	7020K	VS70	OBDII required
KIA	Rio	08-11	31-40	7002, 7002A, or 1206A	1029	2040K	NO	OBDII required
KIA	Rio	12-17	35	7002A	1222	2040K	VS965	OBDII required
KIA	Rio	18-19	71	5001	5510	7020K	VS70	OBDII required
KIA	Rondo	07-10	40	7002 or 7002A	1068	2000K	1096	OBDII required
KIA	Sedona	06-08	40		1028	2000K	1096	OBDII required
KIA	Sedona	09-14	40	7002 or 7002A	1068	2000K	1096	OBDII required
KIA	Sedona	15-18	---	5001	3210	VS20	VS20	OBDII required
KIA	Sedona	19	---		9237	VS20	VS20	OBDII required
KIA	Sorento (with tire display)	07-08	40	7002A	1058	2000K	1096	OBDII required
KIA	Sorento (without tire display)	08-09	40	7002A	1058	2000K	1096	OBDII required
KIA	Sorento	11-13	71	7001HP	5507	7020K	VS70	OBDII required
KIA	Sorento	14-15	71	7003A	5508	7020K	VS70	OBDII required
KIA	Sorento	16-17	71	5001	5510	7020K	VS70	OBDII required
KIA	Sorento	18-19	71	5001	5523	7020K	VS70	OBDII required
KIA	Soul	10-13	71	7001HP	5507	7020K	VS70	OBDII required
KIA	Soul	14-19	---	5001	3210	VS20	VS20	OBDII required
KIA	Spectra	07-09	31-40	7002, 7002A, or 1206A	1029	2040K	NO	OBDII required
KIA	Sportage	06-08	40	7002A	1058	2000K	1096	OBDII required
KIA	Sportage	09-13	31-40	7002, 7002A, or 1206A	1029	2040K	NO	OBDII required
KIA	Sportage	14-16	35		2510	2040K	VS965	OBDII required
KIA	Sportage	17-19	71	5001	5523	7020K	VS70	OBDII required
KIA	Stinger	18-19	---		NEW	VS20	VS20	OBDII required
Lamborghini	Aventador	12-17	40		9011	1096	1096	No tools needed
Lamborghini	Gallardo	08-14	40		9011	1096	1096	No tools needed
Lamborghini	Huracan	15-17	40		9011	1096	1096	No tools needed
Lamborghini	Murcielago	08-10	40		9011	1096	1096	No tools needed
Land Rover	Discovery	17-19	71	5001	5276	7020K	VS70	Auto-relearn
Land Rover	Discovery Sport	15	71	5001	5328 or 5276	7020K	VS70	Auto-relearn
Land Rover	Discovery Sport	16-19	71	5001	5276	7020K	VS70	Auto-relearn
Land Rover	Evoque (315MHz)**	12-14	71		1045**	7020K	VS70	Auto-relearn
Land Rover	Evoque (433MHz)**	14-15	71	5001	5328 or 5276**	7020K	VS70	Auto-relearn
Land Rover	Evoque	16-19	71	5001	5276	7020K	VS70	Auto-relearn
Land Rover	LR2	08-10	71		1045	1050K	NO	Auto-relearn
Land Rover	LR2	10-15	71		1045	7020K	VS70	Auto-relearn
Land Rover	LR3	06-09	71	7001HP	1055	1050K	NO	Auto-relearn
Land Rover	LR4 (315MHz)**	10-14	71		1045**	7020K	VS70	Auto-relearn
Land Rover	LR4 (433MHz)**	13-15	71	5001	5328 or 5276**	7020K	VS70	Auto-relearn
Land Rover	LR4	16	71	5001	5276	7020K	VS70	Auto-relearn
Land Rover	Range Rover	03-05	35		9003	1090K	1092	No tools needed
Land Rover	Range Rover	06-09	71	7001HP	1055	1050K	NO	Auto-relearn
Land Rover	Range Rover (315MHz)**	10-14	71		1045**	7020K	VS70	Auto-relearn
Land Rover	Range Rover (433MHz)**	14-15	71	5001	5328 or 5276**	7020K	VS70	Auto-relearn
Land Rover	Range Rover	16-19	71	5001	5276	7020K	VS70	Auto-relearn
Land Rover	Range Rover Sport	06-09	71	7001HP	1055	1050K	NO	Auto-relearn
Land Rover	Range Rover Sport (315MHz)**	10-14	71		1045**	7020K	VS70	Auto-relearn
Land Rover	Range Rover Sport (433MHz)**	14-15	71	5001	5328 or 5276**	7020K	VS70	Auto-relearn
Land Rover	Range Rover Sport	16-19	71	5001	5276	7020K	VS70	Auto-relearn
Land Rover	Range Rover Velar	18-19	71	5001	5276	7020K	VS70	Auto-relearn
** Note: Utilize the VIN on MY 2013 - 14 vehicles in determining the correct sensor frequency.								
Lexus	CT200h	11-17	35	7002, 7002A, or 1204A	1204	1100K	NO	OBDII required

Verify Model Year by checking the 10th digit in the VIN: 8 = 2008MY, 9 = 2009MY, A = 2010MY, B = 2011MY, etc.

Visit [dillvalves.com](http://dillvalves.com) for vehicle look-ups containing parts, pictures, relearns and training videos

Need Additional Help? Call 800-815-3455, option 3 for technical support

# DILL TPMS APPLICATIONS CHART ©

(Row Color designates the required replacement parts kit for the OE sensor.)

Make	Model	Model Year Range	OE Torque In-Lbs	Dill Replacement Sensor	Dill OEM Sensor	Dill Kit	Valve Stem Replacement	Simplified Relearn
Lexus	ES	07-12	35	7002, 7002A, or 1204A	1204	1100K	NO	OBDII required
Lexus	ES	13-18	35		1218	1100K	NO	OBDII required
Lexus	ES	19	35	7003A	1230	1100K	NO	Trigger required
Lexus	GS	06-11	35	7002, 7002A, or 1204A	1204	1100K	NO	OBDII required
Lexus	GS	13-19	35		1218	1100K	NO	OBDII required
Lexus	GX	03-06	35	7002* or 1204A or 7002A*	1204	1110K	NO	OBDII required
Lexus	GX	07-09	35	7002* or 1204A or 7002A*	1204	1100K	NO	OBDII required
Lexus	GX	10-17	35	7002, 7002A, or 1204A	1204	1100K	NO	OBDII required
Lexus	GX	18-19	35		1218	1100K	NO	OBDII required
Lexus	HS250h	10-12	35	7002, 7002A, or 1204A	1204	1100K	NO	OBDII required
Lexus	IS	06-13	35	7002* or 1204A or 7002A*	1204	1100K	NO	OBDII required
Lexus	IS C	14-15	35	7002, 7002A, or 1204A	1204	1100K	NO	OBDII required
Lexus	IS F (V8 only)	14	35	7002, 7002A, or 1204A	1204	1100K	NO	OBDII required
Lexus	IS250 / IS350 4dr.	14-15	35		1218	1100K	NO	OBDII required
Lexus	IS	16-19	35		1218	1100K	NO	OBDII required
Lexus	LC 500	18-19	35	7003A	1230	1100K	NO	Trigger required
Lexus	LFA	11-13	35	7002, 7002A, or 1204A	1204	1100K	NO	OBDII required
Lexus	LS	07-12	35	7002, 7002A, or 1204A	1204	1100K	NO	OBDII required
Lexus	LS	13-17	35		1218	1100K	NO	OBDII required
Lexus	LS	18-19	35	7003A	1230	1100K	NO	Trigger required
Lexus	LX	06-15	35	7002, 7002A, or 1204A	1204	1100K	NO	OBDII required
Lexus	LX	16-19	35	7003A	1230	1100K	NO	OBDII required
Lexus	NX	15-19	35		1218	1100K	NO	OBDII required
Lexus	RC and RC-F	15-19	35		1218	1100K	NO	OBDII required
Lexus	RX	07-14	35	7002, 7002A, or 1204A	1204	1100K	NO	OBDII required
Lexus	RX (made in Canada)	15	35	7002, 7002A, or 1204A	1204	1100K	NO	OBDII required
Lexus	RX (made in Japan)	15	35	7003A	1230	1100K	NO	OBDII required
Lexus	RX	16-19	35	7003A	1230	1100K	NO	OBDII required
Lexus	SC430**	02-06	27		1217-WH 1217-BL 1217-RD 1217-YL**	1120K	NO	Dealer OBD only
Lexus	SC430	07-10	35	7002, 7002A, or 1204A	1204	1100K	NO	OBDII required
Lexus	UX	19	35	7003A	1230	1100K	NO	Trigger required

\* Note: 406K is needed if the valve hole's counterbore diameter is small than a US dime coin (0.70in).

\*\* Note: Dealer tool is required for the relearn.

Lincoln	Aviator	03-05	44	7004**	9096	1060K	NO	Trigger required
Lincoln	Continental	17-19	---	7003A	9280	VS20	VS20	Auto-relearn
Lincoln	Mark LT	07-08	---	7001HP-R	1048	Banded	NO	Trigger required
Lincoln	MKC	15-17	---	7001HP-R	9315	VS950	VS950	Trigger required
Lincoln	MKC	18-19	---	7003A	9280	VS20	VS20	Auto-relearn
Lincoln	MKS	09-10	---	7001HP-R	1048	Banded	NO	Trigger required
Lincoln	MKS	11-16	---	7001HP-R	9315	VS950	VS950	Trigger required
Lincoln	MKT	10	---	7001HP-R	1048	Banded	NO	Trigger required
Lincoln	MKT	11-19	---	7001HP-R	9315	VS950	VS950	Trigger required
Lincoln	MKX	07-10	---	7001HP-R	1048	Banded	NO	Trigger required
Lincoln	MKX	11-15	---	7001HP-R	9315	VS950	VS950	Trigger required
Lincoln	MKX	16-18	---	7003A	9280	VS20	VS20	Auto-relearn
Lincoln	MKZ	08-09	---	7001HP-R	1048	Banded	NO	Trigger required
Lincoln	MKZ	10-16	---	7001HP-R	9315	VS950	VS950	Trigger required
Lincoln	MKZ	17-19	---	7003A	9280	VS20	VS20	Auto-relearn
Lincoln	Nautilus	19	---	7003A	9280	VS20	VS20	Auto-relearn
Lincoln	Navigator	03-04	44	7004**	9096	1060K	NO	Trigger required
Lincoln	Navigator	05-06	44	7001HP**	9135	1060K	NO	Trigger required

Verify Model Year by checking the 10th digit in the VIN: 8 = 2008MY, 9 = 2009MY, A = 2010MY, B = 2011MY, etc.

Visit [dillvalves.com](http://dillvalves.com) for vehicle look-ups containing parts, pictures, relearns and training videos

Need Additional Help? Call 800-815-3455, option 3 for technical support

# DILL TPMS APPLICATIONS CHART ©

(Row Color designates the required replacement parts kit for the OE sensor.)

Make	Model	Model Year Range	OE Torque In-Lbs	Dill Replacement Sensor	Dill OEM Sensor	Dill Kit	Valve Stem Replacement	Simplified Relearn
Lincoln	Navigator	07-10	---	7001HP-R	1048	Banded	NO	Trigger required
Lincoln	Navigator	11-17	---	7001HP-R	9315	VS950	VS950	Trigger required
Lincoln	Navigator	18-19	---	7003A	9280	VS20	VS20	Auto-relearn
Lincoln	Town Car	08-11	---	7001HP-R	1048	Banded	NO	Trigger required
<b>** Note: Redi-Sensor relearn must be performed with a scan tool, not a magnet.</b>								
Lotus	Elise	08-11	44	5001	9159	2010K	NO	Auto-relearn
Lotus	Evora	10-17	44	5001	9159	2010K	NO	Auto-relearn
Lotus	Exige	08-11	44	5001	9159	2010K	NO	Auto-relearn
Maserati	Coupe/Spyder	05-06	35		9001	1090K	1092 or 1094	
Maserati	GranTurismo	08-10	35		9001	1090K	1092	No tools needed
Maserati	GranTurismo	11-18	40		9011	1096	1096	No tools needed
Maserati	Ghibli	14-18	71	5001	NEW	1100K	VS40	Auto-relearn
Maserati	Levante	17-19	71	5001	9214	1100K	VS40	Auto-relearn
Maserati	Quattroporte	05-10	35		9001	1090K	1092	No tools needed
Maserati	Quattroporte	11-13	40		9011	1096	1096	No tools needed
Maserati	Quattroporte	14-18	71	5001	NEW	1100K	VS40	Auto-relearn
Mazda	B-Series	07-09	---	7001HP-R	1048	Banded	NO	Auto-relearn
Mazda	CX-3	19	71	7001HP	1056	7020K	VS70	Auto-relearn
Mazda	CX-5	17-18	71	7001HP	1056	7020K	VS70	Auto-relearn
Mazda	CX-7	07-10	71	7001HP	1056	1050K	NO	Auto-relearn
Mazda	CX-7	10-12	71	7001HP	1056	7020K	VS70	Auto-relearn
Mazda	CX-9	07-10	71	7001HP	1056	1050K	NO	Auto-relearn
Mazda	CX-9	10-15	71	7001HP	1056	7020K	VS70	Auto-relearn
Mazda	CX-9	18-19	71	7001HP	1056	7020K	VS70	Auto-relearn
Mazda	2	11-14	71	7001HP	1056	7020K	VS70	Auto-relearn
Mazda	3	04	71	7001HP	1056	1130K	NO	Auto-relearn
Mazda	3	05-10	71	7001HP	1056	1050K	NO	Auto-relearn
Mazda	3	10-13	71	7001HP	1056	7020K	VS70	Auto-relearn
Mazda	5	06-10	71	7001HP	1056	1050K	NO	Auto-relearn
Mazda	5	10-15	71	7001HP	1056	7020K	VS70	Auto-relearn
Mazda	6	08-10	71	7001HP	1056	1050K	NO	Auto-relearn
Mazda	6	10-13	71	7001HP	1056	7020K	VS70	Auto-relearn
Mazda	MAZDA6	18	71	7001HP	1056	7020K	VS70	Auto-relearn
Mazda	MX-5 Miata	06-10	71	7001HP	1056	1050K	NO	Auto-relearn
Mazda	MX-5 Miata	10-15	71	7001HP	1056	7020K	VS70	Auto-relearn
Mazda	MX-5 Miata	18-19	71	7001HP	1056	7020K	VS70	Auto-relearn
Mazda	RX-8	04	71	7001HP	1056	1130K	NO	Auto-relearn
Mazda	RX-8	05-10	71	7001HP	1056	1050K	NO	Auto-relearn
Mazda	RX-8	10-11	71	7001HP	1056	7020K	VS70	Auto-relearn
Mazda	Tribute	05-08	---	7001HP-R	1048	Banded	NO	Auto-relearn
Mazda	Tribute	09-11	---	7001HP-R	9315	VS950	VS950	Auto-relearn
McLaren	MP4-12c	12-14	40		9011	1096	1096	Auto-relearn
McLaren	P1	14-15	40		9011	1096	1096	Auto-relearn
McLaren	570GT	17	40	5001	9018	1096	1096	Auto-relearn
McLaren	570S	16	40		9011	1096	1096	Auto-relearn
McLaren	650S	15-16	40		9011	1096	1096	Auto-relearn
McLaren	675LT	16	40		9011	1096	1096	Auto-relearn
M-Benz	AMG GT	16-18	71	5001	9214	1100K	VS40	No tools needed
M-Benz	B-Class	14-17	71	5001	9214	1100K	VS40	No tools needed
M-Benz	C-Class	08-14	53	5001	9214	2030K	9066K	No tools needed
M-Benz	C-Class	15-19	71	5001	9214	1100K	VS40	No tools needed
M-Benz	CL-Class	01-06	35		9004	1090K	1094	No tools needed
M-Benz	CL-Class	07-09	53	7003 or 7003A*	1054	1040K	1040K	Trigger required!
M-Benz	CL-Class	10-14	53	5001	9214	2030K	9066K	No tools needed
M-Benz	CLA-Class	14-19	71	5001	9214	1100K	VS40	No tools needed
M-Benz	CLK-Class	08-09	53	5001	9214	2030K	9066K	No tools needed
M-Benz	CLS-Class	06-11	53	7003 or 7003A*	1054	1040K	1040K	Trigger required!
M-Benz	CLS-Class	12-14	53	5001	9214	2030K	9066K	No tools needed
M-Benz	CLS-Class	15-18	71	5001	9214	1100K	VS40	No tools needed
M-Benz	CLS-Class	19	71	5001	9077	1100K	VS40	No tools needed
M-Benz	E-Class	03-06	35		9004	1090K	1094	No tools needed
M-Benz	E-Class	07-09	53	7003 or 7003A*	1054	1040K	1040K	Trigger required!
M-Benz	E-Class	10-14	53	5001	9214	2030K	9066K	No tools needed
M-Benz	E-Class	15-16	71	5001	9214	1100K	VS40	No tools needed
M-Benz	E-Class 2dr.	17	71	5001	9214	1100K	VS40	No tools needed
M-Benz	E-Class sedan and wagon	17	71	5001	9077	1100K	VS40	No tools needed
M-Benz	E-Class	18-19	71	5001	9077	1100K	VS40	No tools needed
M-Benz	G-Class	07-15	53	5001	9214	2030K	9066K	No tools needed
M-Benz	G-Class	16-19	71	5001	9214	1100K	VS40	No tools needed

Verify Model Year by checking the 10th digit in the VIN: 8 = 2008MY, 9 = 2009MY, A = 2010MY, B = 2011MY, etc.

Visit [dillvalves.com](http://dillvalves.com) for vehicle look-ups containing parts, pictures, relearns and training videos

Need Additional Help? Call 800-815-3455, option 3 for technical support

# DILL TPMS APPLICATIONS CHART ©

(Row Color designates the required replacement parts kit for the OE sensor.)

Make	Model	Model Year Range	OE Torque In-Lbs	Dill Replacement Sensor	Dill OEM Sensor	Dill Kit	Valve Stem Replacement	Simplified Relearn
M-Benz	GL-Class	07-09	53	5001	1049	1040K	1040K	No tools needed
M-Benz	GL-Class	10-14	53	5001	9214	2030K	9066K	No tools needed
M-Benz	GL-Class	15-16	71	5001	9214	1100K	VS40	No tools needed
M-Benz	GLA-Class	15-19	71	5001	9214	1100K	VS40	No tools needed
M-Benz	GLC-Class	16-19	71	5001	9214	1100K	VS40	No tools needed
M-Benz	GLE-Class	16-19	71	5001	9214	1100K	VS40	No tools needed
M-Benz	GLK-Class	10-14	53	5001	9214	2030K	9066K	No tools needed
M-Benz	GLK-Class	15	71	5001	9214	1100K	VS40	No tools needed
M-Benz	GLS-Class	17-19	71	5001	9214	1100K	VS40	No tools needed
M-Benz	Maybach S-Class	16-19	71	5001	9214	1100K	VS40	No tools needed
M-Benz	Metris	16-19	---	5001	NEW	VS20	VS20	No tools needed
M-Benz	ML-Class	07-09	53	5001	1049	1040K	1040K	No tools needed
M-Benz	ML-Class	10-14	53	5001	9214	2030K	9066K	No tools needed
M-Benz	ML-Class	15	71	5001	9214	1100K	VS40	No tools needed
M-Benz	R-Class	07-09	53	5001	1049	1040K	1040K	No tools needed
M-Benz	R-Class	10-12	53	5001	9214	2030K	9066K	No tools needed
M-Benz	S-Class	01-06	35		9004	1090K	1094	No tools needed
M-Benz	S-Class	07-09	53	7003 or 7003A*	1054	1040K	1040K	Trigger required'
M-Benz	S-Class	10-14	53	5001	9214	2030K	9066K	No tools needed
M-Benz	S-Class	15-19	71	5001	9214	1100K	VS40	No tools needed
M-Benz	SL-Class	03-05	35		9004	1090K	1094	No tools needed
M-Benz	SL-Class	06-12	53	7003 or 7003A*	1054	1040K	1040K	Trigger required'
M-Benz	SL-Class	13-14	53	5001	9214	2030K	9066K	No tools needed
M-Benz	SL-Class	15-19	71	5001	9214	1100K	VS40	No tools needed
M-Benz	SLC-Class	17-19	71	5001	9214	1100K	VS40	No tools needed
M-Benz	SLK-Class	08-14	53	5001	9214	2030K	9066K	No tools needed
M-Benz	SLK-Class	15-16	71	5001	9214	1100K	VS40	No tools needed
M-Benz	SLR McLaren (315 MHz)	05-07	35		9004	1090K	1094	No tools needed
M-Benz	SLR McLaren (433 MHz)	05-07	35		9001	1090K	1094	No tools needed
M-Benz	SLR McLaren (315 MHz)	08-09	53	7003 or 7003A*	1054	1040K	1040K	Trigger required'
M-Benz	SLR McLaren (433 MHz)	08-09	53	5001	1049	1040K	1040K	No tools needed
M-Benz	SLS AMG	11-15	53	5001	9214	2030K	9066K	No tools needed
M-Benz	Sprinter (315MHz)	07-13	54	7003 or 7003A*	1042	1098K	1098K	Trigger required'
M-Benz	Sprinter (433MHz)	13-17	53	5001	9214	2030K	9066K	No tools needed
M-Benz	Sprinter	18	71	5001	9214	1100K	VS40	No tools needed
*	Note: 7003A must be scanned while pressurized before the vehicle is driven.							
Mercury	Grand Marquis	08-10	---	7001HP-R	1048	Banded	NO	Trigger required
Mercury	Mariner	05-08	---	7001HP-R	1048	Banded	NO	Trigger required
Mercury	Mariner	09-11	---	7001HP-R	9315	VS950	VS950	Trigger required
Mercury	Milan	08-09	---	7001HP-R	1048	Banded	NO	Trigger required
Mercury	Milan	10-11	---	7001HP-R	9315	VS950	VS950	Trigger required
Mercury	Monterey	06-07	---	7001HP-R	1048	Banded	NO	Trigger required
Mercury	Mountaineer	03-05	44	7004**	9096	1060K	NO	Trigger required
Mercury	Mountaineer	06-10	---	7001HP-R	1048	Banded	NO	Trigger required
Mercury	Sable	08-09	---	7001HP-R	1048	Banded	NO	Trigger required
**	Note: Redi-Sensor relearn must be performed with a scan tool, not a magnet.							
Mini	All models	07-09	35		1027	1090K	1091-1095	No tools needed
Mini	All models	10-13	40	5001	9012	1096	1096	No tools needed
Mini	Cabrio	14	40	5001	9012	1096	1096	No tools needed
Mini	Cabrio (Post March 2014)	14-15	40	5001	9017	1096	1096	No tools needed
Mini	Cabrio	16-19	71	5001	5256	7020K	VS70	No tools needed
Mini	Clubman	14	40	5001	9012	1096	1096	No tools needed
Mini	Clubman (Post July 2014)	14-19	71	5001	5256	7020K	VS70	No tools needed
Mini	Countryman	14	40	5001	9012	1096	1096	No tools needed
Mini	Countryman (Post March 2014)	14-16	40	5001	9017	1096	1096	No tools needed
Mini	Countryman	17-19	71	5001	5256	7020K	VS70	No tools needed
Mini	Coupe	14	40	5001	9012	1096	1096	No tools needed
Mini	Coupe (Post March 2014)	14-15	40	5001	9017	1096	1096	No tools needed
Mini	Hatchback	14-19	71	5001	5256	7020K	VS70	No tools needed
Mini	Paceman	14	40	5001	9012	1096	1096	No tools needed
Mini	Paceman (Post March 2014)	14-16	40	5001	9017	1096	1096	No tools needed
Mini	Roadster	14	40	5001	9012	1096	1096	No tools needed
Mini	Roadster (Post March 2014)	14-15	40	5001	9017	1096	1096	No tools needed
Mitsubishi	Eclipse (w/ Alloy wheels)	08-12	45-53	7001HP	9034	1080K	NO	OBDII required
Mitsubishi	Eclipse (w/ Steel wheels)	08-09	45-53	7001HP	9069	1130K	NO	OBDII required
Mitsubishi	Eclipse Cross	18-19	---	7001HP-R**	NEW	VS90	VS90	OBDII required
Mitsubishi	Endeavor	04-06	45-53	7004	9028	1080K	NO	OBDII required
Mitsubishi	Endeavor (w/ Steel wheels)	07-08	45-53	7001HP	9069	1130K	NO	OBDII required
Mitsubishi	Endeavor (w/ Alloy wheels)	07-11	45-53	7001HP	9034	1080K	NO	OBDII required

Verify Model Year by checking the 10th digit in the VIN: 8 = 2008MY, 9 = 2009MY, A = 2010MY, B = 2011MY, etc.

Visit [dillvalves.com](http://dillvalves.com) for vehicle look-ups containing parts, pictures, relearns and training videos

Need Additional Help? Call 800-815-3455, option 3 for technical support

**DILL TPMS APPLICATIONS CHART ©**

(Row Color designates the required replacement parts kit for the OE sensor.)

Make	Model	Model Year Range	OE Torque In-Lbs	Dill Replacement Sensor	Dill OEM Sensor	Dill Kit	Valve Stem Replacement	Simplified Relearn
Mitsubishi	Galant	06	45-53	7004	9028	1080K	NO	OBDII required
Mitsubishi	Galant (w/ Alloy wheels)	07-12	45-53	7001HP	9034	1080K	NO	OBDII required
Mitsubishi	Galant (w/ Steel wheels)	07-09	45-53	7001HP	9069	1130K	NO	OBDII required
Mitsubishi	i-MiEV**	12-17	71	7001HP**	1051**	7020K	VS70	OBDII required
Mitsubishi	Lancer**	08-10	71	7001HP**	1051**	1050K	NO	OBDII required
Mitsubishi	Lancer**	10-17	71	7001HP**	1051**	7020K	VS70	OBDII required
Mitsubishi	Mirage (snap-in)**	14-18	---	7001HP-R**	NEW	VS90	VS90	OBDII required
Mitsubishi	Mirage (clamp-in)**	14-15	71	7001HP**	1051**	7020K	VS70	OBDII required
Mitsubishi	Montero (w/ Alloy wheels)	03-06	45-53		9034	1080K	NO	Dealer OBD only
Mitsubishi	Montero (w/ Steel wheels)	03-06	45-53		9069	1130K	NO	Dealer OBD only
Mitsubishi	Outlander**	07-10	71	7001HP**	1051**	1050K	NO	OBDII required
Mitsubishi	Outlander and Sport**	10-17	71	7001HP**	1051**	7020K	VS70	OBDII required
Mitsubishi	Outlander and Sport (clamp-in)	18	71	7001HP**	1051**	7020K	VS70	OBDII required
Mitsubishi	Outlander and Sport (snap-in)	18-19	---	7001HP-R**	NEW	VS90	VS90	OBDII required
Mitsubishi	Outlander Sport**	13	---	7001HP-R**	NEW	VS90	VS90	OBDII required
Mitsubishi	Raider	08-09	53	7001HP	9154	9066K	9066K	OBDII required
Mitsubishi	RVR (clamp-in)**	11-18	71	7001HP**	1051**	7020K	VS70	OBDII required
Mitsubishi	RVR (snap-in)**	13-18	---	7001HP-R**	NEW	VS90	VS90	OBDII required
** Note: Vehicle relearn will require an additional Mitsubishi-specific activation tool made by Bartec or Ateq.								
Nissan	350Z	03-06	45-60	7001HP	9064	1080K	NO	OBDII required
Nissan	350Z	07-09	50-70	7001HP	9204	2030K	NO	OBDII required
Nissan	370Z	09-10	35	7001HP	9204	1100K	NO	OBDII required
Nissan	370Z (Post June 2010)	10-19	35	7003 or 7003A	1216	1100K	NO	OBDII required
Nissan	Altima	07-11	50-70	7001HP	9204	2030K	NO	OBDII required
Nissan	Altima	12	71	7001HP	5555	7020K	VS70	OBDII required
Nissan	Altima Coupe	13	71	7001HP	5555	7020K	VS70	OBDII required
Nissan	Altima Sedan	13-18	71	7001HP	5556	7020K	VS70	OBDII required
Nissan	Armada (w/ Alloy wheels)	04-07	49	7001HP	9161	1080K	NO	OBDII required
Nissan	Armada (w/ Steel wheels)	05-06	49	7001HP	9069	1130K	NO	OBDII required
Nissan	Armada	08-15	50-70	7001HP	9204	2030K	NO	OBDII required
Nissan	Armada	17	35	5001	1382	1100K	NO	OBDII required
Nissan	Armada	18-19	35		1375	1100K	NO	OBDII required
Nissan	Cube (<11/11)	09-12	50-70	7001HP	9204	2030K	NO	OBDII required
Nissan	Cube 1.8 & 1.8 S CVT (11/11-3/12)	12	50-70	7001HP	9204	2030K	NO	OBDII required
Nissan	Cube-1.8 SL (10/10-11/11)	11-12	71	7003A	5557	7020K	VS70	OBDII required
Nissan	Cube 1.8 & 1.8S (3/12-9/13)	12-13	35	7001HP	9204	1100K	NO	OBDII required
Nissan	Cube 1.8 S CVT (>11/11)	12-14	35	7003 or 7003A	1216	1100K	NO	OBDII required
Nissan	Frontier	03-04	45-60	7001HP	9064	1080K	NO	OBDII required
Nissan	Frontier (w/ Alloy wheels)	05-07	49	7001HP	9161	1080K	NO	OBDII required
Nissan	Frontier (w/ Steel wheels)	05-07	49	7001HP	9069	1130K	NO	OBDII required
Nissan	Frontier	08-14	50-70	7001HP	9204	2030K	NO	OBDII required
Nissan	Frontier (1/12 - 10/13)	12-19	71	7001HP	5555	7020K	VS70	OBDII required
Nissan	Frontier (snap-in)	19	---	7001HP-R	5362	VS90	VS90	OBDII required
Nissan	GT-R	09-18	50-70	7001HP	9204	2030K	NO	OBDII required
Nissan	Juke Base (w/out I-Key <3/12)	11	50-70	7001HP	9204	2030K	NO	OBDII required
Nissan	Juke SV & SL (w/ I-Key-- 7/10 - 7/11)	11	35	7003 or 7003A	1216	1100K	NO	OBDII required
Nissan	Juke (w/ I-Key-- 7/11 - 9/11)	11	71	7003 or 7003A	5557	7020K	VS70	OBDII required
Nissan	Juke Base (w/out I-Key--Post 3/12)	12-15	35	7001HP	9204	1100K	NO	OBDII required
Nissan	Juke (w/ I-Key--Post 2/12)	12-15	35	7003 or 7003A	1216	1100K	NO	OBDII required
Nissan	Juke	16-17	35	7003 or 7003A	1216	1100K	NO	OBDII required
Nissan	Kicks	18-19	---	5001	4750	VS30	VS30	OBDII required
Nissan	Leaf	11	35	7003 or 7003A	1216	1100K	NO	OBDII required
Nissan	Leaf	12-13	35	7003A	1216	1100K	NO	OBDII required
Nissan	Leaf	13-17	71	7003A	5557	7020K	VS70	OBDII required
Nissan	Leaf	18-19	---		5661	VS90	VS90	OBDII required
Nissan	Maxima	07	49	7001HP	9161	1080K	NO	OBDII required
Nissan	Maxima	07-12	50-70	7001HP	9204	2030K	NO	OBDII required
Nissan	Maxima	12-15	71	7001HP	5555	7020K	VS70	OBDII required
Nissan	Maxima	16-18	71	7001HP	5556	7020K	VS70	OBDII required
Nissan	Murano	03-06	45-60	7001HP	9064	1080K	NO	OBDII required
Nissan	Murano	07-12	50-70	7001HP	9204	2030K	NO	OBDII required
Nissan	Murano (Post Nov. 2011)	12-14	35	7001HP	9204	1100K	NO	OBDII required
Nissan	Murano	15-18	71		5556	7020K	VS70	OBDII required
Nissan	NV200	13-17	50-70	7001HP	9204	2030K	NO	OBDII required
Nissan	NV200	18-19	---	7001HP-R	5362	VS90	VS90	OBDII required

Verify Model Year by checking the 10th digit in the VIN: 8 = 2008MY, 9 = 2009MY, A = 2010MY, B = 2011MY, etc.

Visit [dillvalves.com](http://dillvalves.com) for vehicle look-ups containing parts, pictures, relearns and training videos

Need Additional Help? Call 800-815-3455, option 3 for technical support

**DILL TPMS APPLICATIONS CHART ©**

(Row Color designates the required replacement parts kit for the OE sensor.)

Make	Model	Model Year Range	OE Torque In-Lbs	Dill Replacement Sensor	Dill OEM Sensor	Dill Kit	Valve Stem Replacement	Simplified Relearn
Nissan	NV 1500/2500HD/3500HD	12-18	50-70		9342	2030K	NO	OBDII required
Nissan	Pathfinder	03-04	45-60	7001HP	9064	1080K	NO	OBDII required
Nissan	Pathfinder (w/ Steel wheels)	04	49	7001HP	9069	1130K	NO	OBDII required
Nissan	Pathfinder	05-06	49	7001HP	9161	1080K	NO	OBDII required
Nissan	Pathfinder	07-12	50-70	7001HP	9204	2030K	NO	OBDII required
Nissan	Pathfinder	13-18	71		5556	7020K	VS70	OBDII required
Nissan	Qashqai	17-18	---		5661	VS90	VS90	OBDII required
Nissan	Quest (w/ Steel wheels)	04-07	49	7001HP	9069	1130K	NO	OBDII required
Nissan	Quest (w/ Alloy wheels)	04-06	49	7001HP	9161	1080K	NO	OBDII required
Nissan	Quest	07-09	50-70	7001HP	9204	2030K	NO	OBDII required
Nissan	Quest	11-16	35	7003A	1216	1100K	NO	OBDII required
Nissan	Quest	17	---	7003A	1344	VS30	VS30	OBDII required
Nissan	Rogue	08-11	50-70	7001HP	9204	2030K	NO	OBDII required
Nissan	Rogue	12-13	35	7001HP	9204	1100K	NO	OBDII required
Nissan	Rogue Select	14-15	50-70	7001HP	9204	2030K	NO	OBDII required
Nissan	Rogue clamp-in (433 MHz)	14-16	71		5559	7020K	VS70	OBDII required
Nissan	Rogue snap-in (433 MHz)	16-19	---		5661	VS90	VS90	OBDII required
Nissan	Rogue Sport	17-18	---		5661	VS90	VS90	OBDII required
Nissan	Sentra (w/ Alloy wheels)	07-08	49	7001HP	9161	1080K	NO	OBDII required
Nissan	Sentra	07-12	50-70	7001HP	9204	2030K	NO	OBDII required
Nissan	Sentra (> 1/12)	12	35	7001HP	9204	1100K	NO	OBDII required
Nissan	Sentra (> 9/12) w/out I-KEY	13-16	71	7001HP	5555	7020K	VS70	OBDII required
Nissan	Sentra (w/out I-Key)	17-19	---	7001HP-R	5362	VS90	VS90	OBDII required
Nissan	Sentra (> 12/12) w/ I-KEY	13-16	71	7003A	5557	7020K	VS70	OBDII required
Nissan	Sentra (w/ I-Key)	17-19	---	7003A	NEW	VS90	VS90	OBDII required
Nissan	Titan (w/ Alloy wheels)	04-07	49	7001HP	9161	1080K	NO	OBDII required
Nissan	Titan (w/ Steel wheels)	04-07	49	7001HP	9069	1130K	NO	OBDII required
Nissan	Titan (Post April 2007)	07-14	50-70	7001HP	9204	2030K	NO	OBDII required
Nissan	Titan	15	71	7001HP	5555	7020K	VS70	OBDII required
Nissan	Titan XD	16	35	5001	1382	1100K	NO	OBDII required
Nissan	Titan (all)	17-19	35	5001	1382	1100K	NO	OBDII required
Nissan	Versa	07-11	50-70	7001HP	9204	2030K	NO	OBDII required
Nissan	Versa Sedan	12	71	7001HP	5555	7020K	VS70	OBDII required
Nissan	Versa Sedan S and SV	13-16	71	7001HP	5555	7020K	VS70	OBDII required
Nissan	Versa Sedan S and SV	17	---	7001HP-R	5362	VS90	VS90	OBDII required
Nissan	Versa Sedan	18	---	7001HP-R	5362	VS90	VS90	OBDII required
Nissan	Versa Sedan SL	13-16	71	7003A	5557	7020K	VS70	OBDII required
Nissan	Versa Sedan SL	17	---	7003A	NEW	VS90	VS90	OBDII required
Nissan	Versa (key-in ignition)	19	---	7001HP-R	5362	VS90	VS90	OBDII required
Nissan	Versa (push-button ign.)	19	---	7003A	NEW	VS90	VS90	OBDII required
Nissan	Versa Hatchback (Post Jan. 2012)	12-13	35	7001HP	9204	1100K	NO	OBDII required
Nissan	Versa Note S/SR/SV	14-16	71	7001HP	5555	7020K	VS70	OBDII required
Nissan	Versa Note S/SR/SV	17	---	7001HP-R	5362	VS90	VS90	OBDII required
Nissan	Versa Note (w/out I-Key)	18-19	---	7001HP-R	5362	VS90	VS90	OBDII required
Nissan	Versa Note SL	14-16	71	7003A	5557	7020K	VS70	OBDII required
Nissan	Versa Note SL	17	---	7003A	NEW	VS90	VS90	OBDII required
Nissan	Versa Note (w/ I-Key)	18	---	7003A	NEW	VS90	VS90	OBDII required
Nissan	Xterra	03-04	45-60	7001HP	9064	1080K	NO	OBDII required
Nissan	Xterra	05-07	49	7001HP	9161	1080K	NO	OBDII required
Nissan	Xterra (w/ Steel wheels)	05-07	49	7001HP	9069	1130K	NO	OBDII required
Nissan	Xterra (<10/13)	08-13	50-70	7001HP	9204	2030K	NO	OBDII required
Nissan	Xterra	13-14	71	7001HP	5555	7020K	VS70	OBDII required
Nissan	Xterra	15	50-70	7001HP	9204	2030K	NO	OBDII required
Plymouth	Prowler	97-01	62		8004	1077K	NO	Dealer OBD only
Pontiac	G3	09	---		9153	VS950	VS950	OBDII required
Pontiac	G5	08	71	7001HP	7001HP	1050K	NO	Trigger required
Pontiac	G5	09-10	---	7001HP-R	9153	VS950	VS950	Trigger required
Pontiac	G6 (Pre-10/15/07)	08	71	7001HP	7001HP	1050K	NO	Trigger required
Pontiac	G6 (Post-10/15/07)	08-10	---	7001HP-R	9153	VS950	VS950	Trigger required
Pontiac	G8	08-09	---	7001HP-R	9153	VS950	VS950	Trigger required
Pontiac	Grand Prix	07-08	71	7001HP	7001HP	1050K	NO	Trigger required
Pontiac	Grand Prix	08	---	7001HP-R	9153	VS950	VS950	Trigger required
Pontiac	Montana	08-09	62	7001HP	9158	1070K	NO	Trigger required
Pontiac	Solstice	08-09	71	7001HP	7001HP	1050K	NO	Trigger required
Pontiac	Torrent	07-09	71	7001HP	7001HP	1050K	NO	Trigger required
Pontiac	Vibe	08-10	35	7002, 7002A, or 1204A	1204	1100K	NO	OBDII required
Pontiac	Wave	08-10	---		9153	VS950	VS950	OBDII required

Verify Model Year by checking the 10th digit in the VIN: 8 = 2008MY, 9 = 2009MY, A = 2010MY, B = 2011MY, etc.

Visit [dillvalves.com](http://dillvalves.com) for vehicle look-ups containing parts, pictures, relearns and training videos

Need Additional Help? Call 800-815-3455, option 3 for technical support



(Row Color designates the required replacement parts kit for the OE sensor.)

Make	Model	Model Year Range	OE Torque In-Lbs	Dill Replacement Sensor	Dill OEM Sensor	Dill Kit	Valve Stem Replacement	Simplified Relearn
<b>** Note: The 1050K is to be used on the Siemens sensors and the 1070K is to be used on the Schrader sensors.</b>								
Porsche	911	06-08	31-40		9001	1090K	1092	No tools needed
Porsche	911 (non-Turbo)	09-11	31-40		9011	1090K	1092	No tools needed
Porsche	911 Turbo	09	31-40		9001	1090K	1092	No tools needed
Porsche	911 Turbo	10-11	40		9011	1096	1096	No tools needed
Porsche	911	12-16	40		9011	1096	1096	No tools needed
Porsche	911	17-18	40	5001	9018	1096	1096	Auto-relearn
Porsche	918 Spyder	15	40		9011	1096	1096	No tools needed
Porsche	Boxster	06-08	31-40		9001	1090K	1092	No tools needed
Porsche	Boxster	09-11	31-40		9011	1090K	1092	No tools needed
Porsche	Boxster	12-16	40		9011	1096	1096	No tools needed
Porsche	718 Boxster	17-19	40	5001	9018	1096	1096	Auto-relearn
Porsche	Carrera GT	04-06	31-40		9001	1090K	1092	No tools needed
Porsche	Cayenne	03-06	31-40		9005	1090K	1092	No tools needed
Porsche	Cayenne	08-10	31-40		9011	1090K	1092	No tools needed
Porsche	Cayenne	11-14	40		9011	1096	1096	No tools needed
Porsche	Cayenne	15-19	40	5001	9018	1096	1096	Auto-relearn
Porsche	Cayman	06-08	31-40		9001	1090K	1092	No tools needed
Porsche	Cayman	09-10	31-40		9011	1090K	1092	No tools needed
Porsche	Cayman	11-16	40		9011	1096	1096	No tools needed
Porsche	718 Cayman	17-19	40	5001	9018	1096	1096	Auto-relearn
Porsche	Macan	15-18	40	5001	9018	1096	1096	Auto-relearn
Porsche	Panamera	10-11	31-40		9011	1090K	1092	No tools needed
Porsche	Panamera	12-13	40		9011	1096	1096	No tools needed
Porsche	Panamera	14-18	40	5001	9018	1096	1096	Auto-relearn
RAM	1500, 2500, 3500 pickup	11-13	---	5001	9398	VS950	VS950	Auto-relearn
RAM	1500, 2500, 3500 SRW	14-18	---	5001	6815	VS65	VS65	Auto-relearn
RAM	1500 Classic (DS)	19	---	5001	6815	VS65	VS65	Auto-relearn
RAM	1500 (DT)	19	---		3199	VS950	VS950	Auto-relearn
RAM	3500 Dually (Outer Steel Wheel Sensor)	14-18	---	5001	6815	VS65	VS65	Auto-relearn
RAM	3500 Dually (Outer Alloy Wheel Sensor)	14-18	80-125	5001	6829	VS35	VS35	Auto-relearn
RAM	3500 Dually (Inner Rear Wheel Sensor)	14-18	---	5001	6825	VS65	VS65	Auto-relearn
RAM	Cargo Van (C/V)	12-15	---	5001	9398	VS950	VS950	Auto-relearn
RAM	Dakota	11	---	7001HP-R	9308	VS950	VS950	Auto-relearn
RAM	Promaster	14-18	71	5001	9214	1100K	VS40	Auto-relearn
RAM	Promaster City	15-17	71	5001	9214	1100K	VS40	Auto-relearn
Rolls Royce	Cullinan	19	71	5001	9077	1100K	VS40	
Rolls Royce	Dawn	16-17	40	5001	9012	1096	1096	
Rolls Royce	Dawn	18	40	5001	9017	1096	1096	
Rolls Royce	Drophead Coupe	09-14	31-40		1027	1090K	1092 or 1094	
Rolls Royce	Drophead Coupe	15-17	40	5001	9012	1096	1096	
Rolls Royce	Ghost	10-11	31-40		1027	1090K	1092 or 1094	
Rolls Royce	Ghost (Post Sept. 2010)	11-18	40	5001	9012	1096	1096	
Rolls Royce	Phantom	07-11	31-40		1027	1090K	1092 or 1094	
Rolls Royce	Phantom	12-16	40	5001	9012	1096	1096	
Rolls Royce	Phantom	17-18	71	5001	9077	1100K	VS40	
Rolls Royce	Wraith	14-18	40	5001	9012	1096	1096	
Saab	9-3.	03-07	62	5001	9078	2010K	NO	Auto-relearn
Saab	9-3.	08-11	44	5001	9159	2010K	NO	Auto-relearn
Saab	9-4x	11	---	7001HP-R	9153	VS950	VS950	Trigger required
Saab	9-5.	08-09	44	5001	9159	2010K	NO	Auto-relearn
Saab	9-5.	10-11	---	7001HP-R	9153	VS950	VS950	Trigger required
Saab	9-7X	07-09	62	7001HP	9116	1070K	NO	Trigger required
Saturn	Astra	08-09	62	5001	9078	2010K	NO	Auto-relearn
Saturn	Aura (<10/14/07)	07-08	71	7001HP	7001HP	1050K	NO	Trigger required
Saturn	Aura (>10/14/07)	08-09	---	7001HP-R	9153	VS950	VS950	Trigger required
Saturn	Outlook	07-08	71	7001HP	7001HP	1050K	NO	Trigger required
Saturn	Outlook	09-10	---	7001HP-R	9153	VS950	VS950	Trigger required
Saturn	Sky	08-09	71	7001HP	7001HP	1050K	NO	Trigger required
Saturn	Vue	08-10	---	7001HP-R	9153	VS950	VS950	Trigger required
<b>** Note: The 1050K is to be used on the Siemens sensors and the 1070K is to be used on the Schrader sensors.</b>								
Scion	FR-S	13-16	35	7003 or 7003A	1218	1100K	NO	OBDII required
Scion	iM	16	35	7003 or 7003A	1218	1100K	NO	OBDII required
Scion	iQ	12-15	35	7002, 7002A, or 1204A	1204	1100K	NO	OBDII required

Verify Model Year by checking the 10th digit in the VIN: 8 = 2008MY, 9 = 2009MY, A = 2010MY, B = 2011MY, etc.

Visit [dillvalves.com](http://dillvalves.com) for vehicle look-ups containing parts, pictures, relearns and training videos

Need Additional Help? Call 800-815-3455, option 3 for technical support

# DILL TPMS APPLICATIONS CHART ©

(Row Color designates the required replacement parts kit for the OE sensor.)

Make	Model	Model Year Range	OE Torque In-Lbs	Dill Replacement Sensor	Dill OEM Sensor	Dill Kit	Valve Stem Replacement	Simplified Relearn
Scion	tC	07-16	35	7002, 7002A, or 1204A	1204	1100K	NO	OBDII required
Scion	xB	08-15	35	7002, 7002A, or 1204A	1204	1100K	NO	OBDII required
Scion	xD	08-14	35	7002, 7002A, or 1204A	1204	1100K	NO	OBDII required
Smart	Fortwo	08-15	53	5001	9214	2030K	9066K	No tools needed
Smart	Fortwo	16-18	---	5001	NEW	VS20	VS20	No tools needed
Subaru	Ascent	19	---	5001	8023	VS20	VS20	OBDII required
Subaru	B9 Tribeca	06-07	66	7003 or 7003A	9081	1080K	NO	OBDII required
Subaru	BRZ	13-19	35	7003 or 7003A	1218	1100K	NO	OBDII required
Subaru	Crosstrek	16-17	---	7003 or 7003A	9203	VS950	VS950	OBDII required
Subaru	Crosstrek	18-19	---	5001	8023	VS20	VS20	OBDII required
Subaru	Forester	08-18	---	7003 or 7003A	9203	VS950	VS950	OBDII required
Subaru	Forester	19	---	5001	8023	VS20	VS20	OBDII required
Subaru	Impreza	08-16	---	7003 or 7003A	9203	VS950	VS950	OBDII required
Subaru	Impreza	17-19	---	5001	8023	VS20	VS20	OBDII required
Subaru	Legacy	07	66	7003 or 7003A	9081	1080K	NO	OBDII required
Subaru	Legacy	08-17	---	7003 or 7003A	9203	VS950	VS950	OBDII required
Subaru	Legacy	18-19	---	5001	8023	VS20	VS20	OBDII required
Subaru	Outback	05-08	66	7003 or 7003A	9081	1080K	NO	OBDII required
Subaru	Outback	08-17	---	7003 or 7003A	9203	VS950	VS950	OBDII required
Subaru	Outback	18-19	---	5001	8023	VS20	VS20	OBDII required
Subaru	Tribeca	08-14	---	7003 or 7003A	9203	VS950	VS950	OBDII required
Subaru	WRX & STI	15-19	---	7003 or 7003A	9203	VS950	VS950	OBDII required
Subaru	XV Crosstrek	13-15	---	7003 or 7003A	9203	VS950	VS950	OBDII required
Suzuki	Equator	09-12	68	7001HP	9204	2030K	NO	OBDII required
Suzuki	Foreza	07-08	---	7001HP-R	9153	VS950	VS950	Trigger required
Suzuki	Grand Vitara**	07-13	80	---	9087	2010K	NO	OBDII required
Suzuki	Kizashi	10-13	71	7001HP	1051	7020K	VS70	Trigger required
Suzuki	Reno	07-08	---	7001HP-R	9153	VS950	VS950	Trigger required
Suzuki	SX4**	07-13	80	---	9087	2010K	NO	Trigger required
Suzuki	Verona	05-06	80	---	9082	2010K	NO	Trigger required
Suzuki	XL-7	05-06	80	---	9087	2010K	NO	Trigger required
Suzuki	XL-7	07-09	71	7001HP	7001HP	1050K	NO	Trigger required
** Note: Vehicle relearn will require an additional Mitsubishi/Suzuki-specific activation tool made by Bartec.								
Tesla	Roadster (VIN 001-500)	08-10	40	---	9011	1096	1096	No tools needed
Tesla	ALL (BaoLong)	10-14	40-50	---	2112	TP416L	TP416L	---
Tesla	Model S (Silver Continental)	14-18	71	5001	2168	7020K	VS70	Auto-relearn
Tesla	Model S (Black Continental)	14-18	71	5001	2168	7020K	VS70B	Auto-relearn
Tesla	Model X	16-18	71	5001	2168	7020K	VS70	Auto-relearn
Tesla	Model 3	18	71	5001	2168	7020K	VS70	Auto-relearn
Toyota	4Runner	04-17	35	7002, 7002A, or 1204A	1204	1110K	NO	OBDII required
Toyota	4Runner	18-19	35	7002, 7002A, or 1204A	1204	1100K	NO	OBDII required
Toyota	86	17-19	35	7003 or 7003A	1218	1100K	NO	OBDII required
Toyota	Avalon	07-12	35	7002, 7002A, or 1204A	1204	1100K	NO	OBDII required
Toyota	Avalon	13-15	35	7003 or 7003A	1218	1100K	NO	OBDII required
Toyota	Avalon	16-18	35	7003A	1230	1100K	NO	OBDII required
Toyota	Avalon	19	35	7003A	1230	1100K	NO	Trigger required
Toyota	Camry	07-11	35	7002, 7002A, or 1204A	1204	1100K	NO	OBDII required
Toyota	Camry	12-14	35	7003 or 7003A	1218	1100K	NO	OBDII required
Toyota	Camry w/ centered speedometer	15	35	7003 or 7003A	1218	1100K	NO	OBDII required
Toyota	Camry (Lo-Line)	16	35	7003 or 7003A	1218	1100K	NO	OBDII required
Toyota	Camry LE (Lo-Line)	17	35	7003 or 7003A	1218	1100K	NO	OBDII required
Toyota	Camry LE (Hi-Line)	17	35	7003A	1230	1100K	NO	OBDII required
Toyota	Camry w/ centered colored screen	15	35	7003A	1230	1100K	NO	OBDII required
Toyota	Camry (Hi-Line)	16	35	7003A	1230	1100K	NO	OBDII required
Toyota	Camry non-LE	17	35	7003A	1230	1100K	NO	OBDII required
Toyota	Camry Hybrid (all trims)	17	35	7003A	1230	1100K	NO	OBDII required
Toyota	Camry	18	35	7003A	1230	1100K	NO	OBDII required
Toyota	Camry	19	35	7003A	1230	1100K	NO	Trigger required
Toyota	C-HR	18-19	35	7003A	1230	1100K	NO	OBDII required
Toyota	Corolla	07-13	35	7002, 7002A, or 1204A	1204	1100K	NO	OBDII required
Toyota	Corolla (all)	14-18	35	7003 or 7003A	1218	1100K	NO	OBDII required

Verify Model Year by checking the 10th digit in the VIN: 8 = 2008MY, 9 = 2009MY, A = 2010MY, B = 2011MY, etc.

Visit [dillvalves.com](http://dillvalves.com) for vehicle look-ups containing parts, pictures, relearns and training videos

Need Additional Help? Call 800-815-3455, option 3 for technical support

# DILL TPMS APPLICATIONS CHART ©

(Row Color designates the required replacement parts kit for the OE sensor.)

Make	Model	Model Year Range	OE Torque In-Lbs	Dill Replacement Sensor	Dill OEM Sensor	Dill Kit	Valve Stem Replacement	Simplified Relearn
Toyota	Corolla sedan	19	35	7003 or 7003A	1218	1100K	NO	OBDII required
Toyota	FJ Cruiser	08-14	35	7002** or 1204A or 7002A**	1204	1100K	NO	OBDII required
Toyota	Highlander	07-13	35	7002, 7002A, or 1204A	1204	1100K	NO	OBDII required
Toyota	Highlander (w/ Smart Key)	14-19	35	7003 or 7003A	1218	1100K	NO	OBDII required
Toyota	Highlander (w/out Smart Key)	14-19	35	7003A	1225	1100K	NO	OBDII required
Toyota	Land Cruiser	06-15	35	7002, 7002A, or 1204A	1204	1100K	NO	OBDII required
Toyota	Land Cruiser	16-19	35	7003A	1230	1100K	NO	OBDII required
Toyota	Matrix	07-13	35	7002, 7002A, or 1204A	1204	1100K	NO	OBDII required
Toyota	Mirai	16-18	35	7003 or 7003A	1218	1100K	NO	OBDII required
Toyota	Prius	06-15	35	7002, 7002A, or 1204A	1204	1100K	NO	OBDII required
Toyota	Prius and Prime	16	35	7003 or 7003A	1218	1100K	NO	OBDII required
Toyota	Prius V	12-16	35	7002, 7002A, or 1204A	1204	1100K	NO	OBDII required
Toyota	Prius C	12-18	35	7003 or 7003A	1218	1100K	NO	OBDII required
Toyota	Prius (all trims)	17-18	35	7003 or 7003A	1218	1100K	NO	OBDII required
Toyota	RAV4	06-12	35	7002** or 1204A or 7002A**	1204	1100K	NO	OBDII required
Toyota	RAV4 Electric Vehicle (EV)	13-14	35	7002** or 1204A or 7002A**	1204	1100K	NO	OBDII required
Toyota	RAV4 non-EV (w/ Smart Key)	13-18	35	7003 or 7003A	1218	1100K	NO	OBDII required
Toyota	RAV4 non-EV (Made in Japan w/out Smart Key)	13-18	35	7003 or 7003A	1218	1100K	NO	OBDII required
Toyota	RAV4 non-EV (Made in Canada w/out Smart Key)	13-18	35	7003A	1225	1100K	NO	OBDII required
Toyota	Sequoia (w/ Alloy wheels)	05-07	35	7002, 7002A, or 1204A	1204	1110K	NO	OBDII required
Toyota	Sequoia (w/ Steel wheels)	05-07	35	7002, 7002A, or 1204A	1203	1110K	NO	OBDII required
Toyota	Sequoia (40 Degrees)	08	35	7002, 7002A, or 1206A	1206	1110K	NO	OBDII required
Toyota	Sequoia (20 Degrees)	08-17	35	7002, 7002A, or 1206A	1206	1110K	NO	OBDII required
Toyota	Sequoia	18-19	35		7091	1100K	NO	No tools needed
Toyota	Sienna	07-19	35	7002, 7002A, or 1206A	1206	1110K	NO	OBDII required
Toyota	Solara	07-08	35	7002, 7002A, or 1204A	1204	1100K	NO	OBDII required
Toyota	Tacoma (w/ Alloy wheels)	05-06	35	7002, 7002A, or 1204A	1204	1110K	NO	OBDII required
Toyota	Tacoma (w/ Steel wheels)	05-15	35	7002, 7002A, or 1204A	1203	1110K	NO	OBDII required
Toyota	Tacoma (w/ Steel wheels)	16-19	35	7003A	NEW	1100K	NO	OBDII required
Toyota	Tacoma (w/ Alloy wheels)	07-15	35	7002** or 1204A or 7002A**	1204	1100K	NO	OBDII required
Toyota	Tacoma (w/ Alloy wheels)	16-19	35	7003A	1230	1100K	NO	OBDII required
Toyota	Tundra (w/ Alloy wheels)	05-06	35	7002** or 1204A or 7002A**	1204	1110K	NO	OBDII required
Toyota	Tundra (w/ Steel wheels)	05-06	35	7002, 7002A, or 1204A	1203	1110K	NO	OBDII required
Toyota	Tundra (40 Degrees)	07-11	35	7002, 7002A, or 1206A	1206	1110K	NO	OBDII required
Toyota	Tundra (20 Degrees)	07-17	35	7002, 7002A, or 1206A	1206	1110K	NO	OBDII required
Toyota	Tundra (w/ Alloy wheels)	18-19	35		7091	1100K	NO	No tools needed
Toyota	Tundra (w/ Steel wheels)	18-19	35		7114	1100K	NO	No tools needed
Toyota	Venza	09-15	35	7002, 7002A, or 1204A	1204	1100K	NO	OBDII required
Toyota	Yaris	08-11	35	7002, 7002A, or 1204A	1204	1100K	NO	OBDII required
Toyota	Yaris	12-18	35	7003 or 7003A	1218	1100K	NO	OBDII required
** Note: 406K is needed if the valve hole's counterbore diameter is small than a US dime coin (0.70in).								
Volkswagen	Beetle	08-10	71	7003 or 7003A*	1053	1030K	NO	Trigger required'
Volkswagen	CC	09-11	71	7003 or 7003A*	1053	1030K	NO	Trigger required'
Volkswagen	CC	12-17	40	5001	9013	1096	1096	No tools needed

Verify Model Year by checking the 10th digit in the VIN: 8 = 2008MY, 9 = 2009MY, A = 2010MY, B = 2011MY, etc.

Visit [dillvalves.com](http://dillvalves.com) for vehicle look-ups containing parts, pictures, relearns and training videos

Need Additional Help? Call 800-815-3455, option 3 for technical support

# DILL TPMS APPLICATIONS CHART ©

(Row Color designates the required replacement parts kit for the OE sensor.)

Make	Model	Model Year Range	OE Torque In-Lbs	Dill Replacement Sensor	Dill OEM Sensor	Dill Kit	Valve Stem Replacement	Simplified Relearn	
Volkswagen	Eos	07-16	71	7003 or 7003A*	1053	1030K	NO	Trigger required'	
Volkswagen	GLI	08-09	71	7003 or 7003A*	1053	1030K	NO	Trigger required'	
Volkswagen	Golf	10-11	71	7003 or 7003A*	1053	1030K	NO	Trigger required'	
Volkswagen	GTI	06-11	71	7003 or 7003A*	1053	1030K	NO	Trigger required'	
Volkswagen	GTI w/ OE 18in wheels	06-07	71	7003 or 7003A*	1041	1031K	NO	Trigger required'	
Volkswagen	Jetta	06-11	71	7003 or 7003A*	1053	1030K	NO	Trigger required'	
Volkswagen	Passat	06-10	71	7003 or 7003A*	1053	1030K	NO	Trigger required'	
Volkswagen	Passat w/ OE 18in wheels	06-08	71	7003 or 7003A*	1041	1031K	NO	Trigger required'	
Volkswagen	Phaeton	04-06	35		9001	1090K	1092	No tools needed	
Volkswagen	R32	08	71	7003 or 7003A*	1053	1030K	NO	Trigger required'	
Volkswagen	Rabbit	07-09	71	7003 or 7003A*	1053	1030K	NO	Trigger required'	
Volkswagen	Routan	09-10	71	7004	1043	1050K	NO	Auto-relearn	
Volkswagen	Routan	11-14	---	5001	9398	VS950	VS950	Auto-relearn	
Volkswagen	Tiguan	09-11	71	7003 or 7003A*	1053	1030K	NO	Trigger required'	
Volkswagen	Tiguan	14	40	5001	9013	1096	1096	No tools needed	
Volkswagen	Touareg	04-07	35		9005	1090K	1092	No tools needed	
Volkswagen	Touareg	08-10	35		9011	1090K	1092	No tools needed	
Volkswagen	Touareg	11-14	40		9011	1096	1096	No tools needed	
Volkswagen	Touareg	15-17	40	5001	9018	1096	1096	No tools needed	
*	Note: 7003A must be scanned while pressurized before the vehicle is driven.								
Volvo	C30	08-10	71	7004	1044	1050K	NO	Auto-relearn	
Volvo	C30	11-13	71	7004	1044	7020K	VS70	Auto-relearn	
Volvo	C70	08-10	71	7004	1044	1050K	NO	Auto-relearn	
Volvo	C70	11-13	71	7004	1044	7020K	VS70	Auto-relearn	
Volvo	S40	08-10	71	7004	1044	1050K	NO	Auto-relearn	
Volvo	S40	11	71	7004	1044	7020K	VS70	Auto-relearn	
Volvo	S60	05-08	44	7003 or 7003A	9156	2010K	NO	Auto-relearn	
Volvo	S60	08-09	---	7003 or 7003A	9156	VS950	VS950	Auto-relearn	
Volvo	S60	11-13	71	7004	1044	7020K	VS70	Auto-relearn	
Volvo	S60 (clamp-in)	14-17	71	5001	5134	7020K	VS70	Auto-relearn	
Volvo	S80	05-06	44	7003 or 7003A	9156	2010K	NO	Auto-relearn	
Volvo	S80	07-10	71	7004	1044	1050K	NO	Auto-relearn	
Volvo	S80	10-13	71	7004	1044	7020K	VS70	Auto-relearn	
Volvo	S80 (clamp-in)	14-16	71	5001	5134	7020K	VS70	Auto-relearn	
Volvo	V50	08-10	71	7004	1044	1050K	NO	Auto-relearn	
Volvo	V50	11	71	7004	1044	7020K	VS70	Auto-relearn	
Volvo	V60 (clamp-in)	15-18	71	5001	5134	7020K	VS70	Auto-relearn	
Volvo	V70	05-07	44	7003 or 7003A	9156	2010K	NO	Auto-relearn	
Volvo	V70	08-10	71	7004	1044	1050K	NO	Auto-relearn	
Volvo	XC60	10-13	71	7004	1044	7020K	VS70	Auto-relearn	
Volvo	XC60	14-17	71	5001	5134	7020K	VS70	Auto-relearn	
Volvo	XC70	05-07	44	7003 or 7003A	9156	2010K	NO	Auto-relearn	
Volvo	XC70	08-10	71	7004	1044	1050K	NO	Auto-relearn	
Volvo	XC70	10-13	71	7004	1044	7020K	VS70	Auto-relearn	
Volvo	XC70 (clamp-in)	14-16	71	5001	5134	7020K	VS70	Auto-relearn	
Volvo	XC90 (315 MHz)	05-08	44	7003 or 7003A	9156	2010K	NO	Auto-relearn	
Volvo	XC90 (433 MHz)	08	71	7004	1044	1050K	NO	Auto-relearn	
Volvo	XC90 (315 MHz)	08-14	---	7003 or 7003A	9156	VS950	VS950	Trigger required	
Volvo	XC90 (Direct TPMS)	16-17	---	5001	NEW	VS20	VS20	Auto-relearn	
VPG	MV-1	11-13	---	7001HP-R	9315	VS950	VS950	Trigger required	
Volvo Group	Volvo Bus	all	---		9010	VS9013 or VS9980	VS9013 or VS9980		
Volvo Group	Prevost Bus	all	---		9010	VS9013 or VS9980	VS9013 or VS9980		
Volvo Group	Nova Bus	all	---		9010	VS9013 or VS9980	VS9013 or VS9980		

**DISCLAIMER:** The data presented in this document is accurate to the best of our knowledge and is regularly updated with the latest data available in the marketplace. We encourage you to check back for the latest edition of this data, however, we cannot guarantee accuracy of the information provided. Also, please note that several vehicle applications require knowledge of the VIN number as the sensor design could have changed mid-model year. **PLEASE DO NOT POST THIS DOCUMENT ON ANY WEBSITE.**